


INFRASTRUCTURE ASSESSMENT AUDIT FOR SUVA – NAUSORI URBAN SCHOOLS

DRAIBA PRIMARY SCHOOL (REG 2324)

SUMMARY REPORT





DRAIBA PRIMARY SCHOOL

INFRASTRUCTURE ASSESSMENT FOR (DRAIBA PRIMARY SCHOOL)



TABLE OF CONTENTS

1)	INSPECTION SUMMARY	3
2)	ASSESSMENT OF OVERCROWDING	4
3)	EXISTING INFRASTRUCTURE CONDITIONS	5
4)	WATER SANITATION HYGIENE (WASH) FACILITIES	7
5)	DISASTER RESILIENCE ASSESSMENT	
6)	ACCESSIBILITY ASSESSMENT	
7)	SUMMARY OF FINDINGS	10
8)	RECOMMENDATIONS	
9)	COMPLIANCE	
10)	APPENDIX	



1) INSPECTION SUMMARY

School Inspection Summary	
School name:	DRAIBA PRIMARY SCHOOL
Overall condition state:	FAIR
Var. va cammandations.	

Key recommendations:

- Overcrowding 8 new classrooms required based on FNBC standards
- Overcrowding 3 new classrooms required based on recommended sizing (1.5m²)
- WASH Maintenance of ablution blocks required
- Accessibility -All buildings require accessibility ramps, accessible doorways
- Disaster resilience Windows to include cyclone shutters and roof cladding fastened with Cyclone roofing screws.

Comments:

Major defects were noted as follows:

- Building 4 Deteriorated ceiling framing and ceiling board. Damaged Window Frame.
- Exposed Rotten Veranda Roof Framing
- Ceiling boards were sagging with clear indication of roof leakages.
- Hairline cracks on walls and corridors
- Rusted roof cladding, gutter and roofing nails **Aerial view of school**

General view of school









B11 B10	PG
B2 B9	B6
B4 B4	B5

School type:

| Primary | Secondary | Year | 1,2,3,4,5,6,7,8 |

INFRASTRUCTURE ASSESSMENT FOR (DRAIBA PRIMARY SCHOOL)



School address:	153 Ratu Sukuna Road, Suva						
School enrolment and staff figures	No. of Students (Total)	No. of Students (Female/Male)	S No. of No. of No. Students with Disability (Male)		No. of Teachers (Fe	o. of Teachers (Female)	
	758	-	0	6	15		
School building arrangement	TOTAL NUMBER	OF BUILDINGS: 9					
	B1 – SINGLE STOREY / B2 – SINGLE STOREY / B3 – SINGLE STOREY / B4 – SINGLE STOREY / B5 – SINGLE STOREY / B6 – SINGLE STOREY / B7 – SINGLE STOREY / B8 – SINGLE STOREY / B9 – DOUBLE STOREY B10 – SINGLE STOREY / B11 – SINGLE STOREY						
Local government area:	NASESE, SUVA						
Date of inspection:	09 ND SEPTEMBEF	R, 2024					
Inspection team:	KUNAAL NAND (KN) HENDRY TABULAWAKI (HT) CLIFFTON RAITAVOWAI (CR) MARIA LUTUA (ML)						
Data collection methods	Visual inspection		,	Onsite me	asurement	✓	
	Interviews with sch	nool staff	,	Drone / ae	rial imagery	√	
	Survey form ✓ Desktop research					√	
	Other:						
Assumptions:	NONE						
Limitations:	UNAVAILABILITY	OF ALL SCHOOL I	DOCUMENTS SU	ICH AS BOUN	DARY AREA.		

2) ASSESSMENT OF OVERCROWDING

An assessment for overcrowding was undertaken based on FNBC standards and 2024 enrolment data. The table below summarises the data collected through visual inspection and interrogation of enrolment data and compares this against the FNBC standard student to classroom size ratio of 2 m² per student.

The results of the assessment are based on the recommended sizing (1.5m²), according to 2024 data, an additional 3 classrooms are required for Draiba Primary School.

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS 22403058

Page **4** of **12** Prepared by **NRW** Revision No. A1



Year	Stream	Number of students	Current number of classrooms	Number of extra classrooms required based on FNBC on 2024 data	
1	101	47	2	4	
1	102	44	2	l l	
2	201	44	2	1	
	202	41	2	I	
3	301	44	2	1	
3	302	45	Z	I	
	401	29			
4	402	30	3	-	
	403	28			
	501	31			
5	502	25	3	-	
	503	32			
	601	33			
6	602	30	3	1	
	603	32			
	701	28			
7	702	31	3	-	
	703	31			
	801	38			
8	802	40	3	1	
	803	37			

3) **EXISTING INFRASTRUCTURE CONDITIONS**

Given the outlined procedure, the following observations were made:

Block Code	Length (m)	Width (m)	Height (m)	No. of Levels	Туре	Room List
B1	34	10.1	2.8	1	Single timber structure with cladding on timber framed roof structure and timber external walls	- (4) Classrooms
B2	31.9	9.2	4.1	1	Single concrete structure with cladding on timber framed roof structure and masonry external walls	- (2) Classrooms
В3	12.5	3	2.7	1	Single concrete structure with cladding on timber framed roof structure and masonry external walls	- Boys /Girls Toilet (6-8)
B4	24.1	5.4	3.7	1	Single concrete structure with cladding on timber framed roof structure and masonry external walls	- Classrooms / Girls Toilets (1-4)
B5	28.5	9.1	3.5	1	Single concrete structure with cladding on timber framed roof structure and masonry external	- Classrooms / Storage / Staff Toilet



					wall's structure and masonry external walls	
В6	24.3	9.1	3.7	1	Single concrete structure with cladding on timber framed roof structure and masonry external wall's structure and masonry external walls	- Classroom / Boys toilet (1-4)
В7	17.6	9.5	4	1	Single timber structure with cladding on timber framed roof structure and timber external walls	- Classrooms
В9	19	12.5	5.4	2	Double storey concrete structure with cladding on timber framed roof structure and masonry external walls	- Classrooms / Office / Library
B10	10.2	10.6	4	1	Single timber structure with cladding on timber framed roof structure and timber external walls	- Classrooms
B11	34.6	9.9	3.5	1	Single timber structure with cladding on timber framed roof structure and timber external walls	- Classrooms

Summary Table for Classrooms

This table provides a quick overview of the assessment findings, helping to identify areas that need immediate attention and those that are in good condition. The following criteria was used:

- Good No additional works / intervention required
- Fair Remedial works required
- Poor Demolition and replace with new

Assessment Area	Criteria	Conditions
Structural Integrity	Walls, ceiling, floor, foundation and roofs	Poor
General upkeep	Exterior, interior, furniture and fixtures	Poor
Safety compliance	Fire safety, electrical safety,	Fair
Disability	Accessibility	Poor
Ventilation and lighting	Ventilations, Natural Lighting, Artificial Lighting.	Fair

Observations on Structural Elements

- > Walls and Ceiling Cracks on concrete observed. There were water leak marks on the ceiling and there are signs of wear and tear on walls.
- Floors and Foundation the floor and foundation for the entire school is found to be in a fair condition. There is visible sign of cracks on the concrete floors and the foundation columns.
- Roofs the school reported that there are leaks in some places. It was found that roof materials are in fair condition. However, some roof cladding and fastenings are partially rusted and requires upgrading works.
- ➤ Windows some missing window louvre blades were recorded at various buildings

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS 22403058 PROJECT NUMBER:

PROIFCT NAME:

SCHOOL NAME: DRAIBA PRIMARY SCHOOL Page **6** of **12** Prepared by **NRW** Revision No. A1



- **Earthquake** The single-storey main concrete building indicates non-resistance to earthquake based on suitable column, beam and slab size and design.
- > Cyclone minor roof upgrading works required to increase cyclone resilient capacity of the structures.

Existing Conditions of Building and Maintenance

- **Exterior** the building is in fair condition as the wall, beam, column, window seal, doors, eaves, fascia boards and gutters are intact and coated with paint. The school executes periodical maintenance.
- ➤ Interior the building is in fair condition as the walls, beams, columns windows, doors and ceiling are intact and coated with paint. The school executes periodical maintenance. The classrooms were found to be clean with proper waste disposal.
- Furniture and Fixtures the classrooms and offices have adequate furniture and fixtures that do not impede on the function of the buildings.

Safety and compliance with standards

- Fire Safety the school does not possess adequate fire safety mechanisms. Present fire extinguishers need maintenance and commissioning. No fire hydrants and alarm systems were found. The school has Emergency exit plan and designated assembly area provisioned.
- ➤ Electrical Safety The school is connected to EFL Grid. The school has surface wiring with no fault outlets. All electrical systems are measured to be safe.
- ➤ Accessibility the school does not meet disability accessibility standards. The school does not have facilities such as ramps, handrails and accessible restrooms.

Lighting and Ventilation

- **Ventilation** HVAC system (Heating, Ventilation, and Air Conditioning) is centrally located in the school, in particular the administration office as well as the computer lab.
- Natural Lighting there are adequate number of windows installed in classrooms, that are regularly cleaned to allow natural light to enter into classrooms unobstructed.
- > Artificial Lighting it was found that all light fixtures are working and provides adequate illumination.

4) WATER SANITATION HYGIENE (WASH) FACILITIES

Condition of Toilets and Washrooms

Draiba Primary School has toilet facilities in 2 blocks. The toilet facilities have some minor defects such as:

- The cubicle doors were damaged/missing.
- Some toilet seat pans were missing.
- Rust was found on the door hinges and steel connectors of the PVC pipe outlets in the toilet system.

PROJECT NAME: INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS
PROJECT NUMBER: 22403058
SCHOOL NAME: DRAIBA PRIMARY SCHOOL



The WASH facilities were unclean and lacked maintenance.

The table below presents wash facilities data.

TOILET CUBICLE(S)		No. of Cubicles		Toilet Ratio (1 cubicle: students)		Compliance of Student to Toilet Cubicle Ratio (FNBC).	
Building Index	Used by Years	Female	Male	Female	Male	Female Requirement (1:20) Extra Toilets?	Male Requirement (1:30) Extra Toilets?
В3	6-8	5	5	30	30	2	2
В4	1-4	7	-	25	-	0	0
В6	1-4	-	4	-	44	-	2

HAND	HAND BASINS IN THE TOILET		No. of Hand Basins		Handbasin Ratio 1:		Compliance of Student to Hand Basin Ratio (FNBC).	
Building Index	Used by Years	Female	Male	Female	Male	Female Requirement (1:60) Extra Handbasins?	Male Requirement (1:60) Extra Handbasins?	
В3	6-8	1	1	150	150	3	3	
В4	1-4	1	-	175	-	3	3	
В6	1-4	-	1		175	3	3	

GENERAL OUTDOOR TAPS		No. of General Outdoor Taps	Outdoor Taps Ratio 1:	Compliance of Student to Outdoor Taps Ratio Requirement (1:60) (FNBC) Does it require additional hand basins?
Building Index	Used by Years			
All buildings	All years	12	60	0



5) <u>DISASTER RESILIENCE ASSESSMENT</u>

This infrastructure condition assessment aims to evaluate the architectural, structural, and non-structural features of the school to ensure it is resilient to natural disasters and provides a safe learning environment for students. The assessment also identifies areas for improvement and highlights the measures already in place to enhance overall resilience. FNBC 1990 and basic loading, wind and seismic AS/NZS codes typical details were utilized during and after inspection.

Architectural

- Cyclonic Roof: The school has a cyclonic roof designed to withstand strong winds and seismic activity. However, replacement with new roof cladding and roofing screws is needed.
- Location: The school is location allows easy access to main streets and relief services.

Structural

- Material Quality: The school buildings are constructed using reinforced concrete and follow acceptable
 engineering design principles.
- Structural Integrity: Buildings have demonstrated the capability to withstand and recover from natural disasters like earthquakes, category 3 cyclones, and floods.

Non-Structural

- Disaster Preparedness: Implementation of disaster evacuation plans, emergency exit routes, and safety protocols.
- Fire Safety: Strategically placed fire extinguishers to mitigate fire-related risks.

6) ACCESSIBILITY ASSESSMENT

1. Compliance with Accessibility Standards:

Educational facilities did not meet accessibility standards, such as the Fiji Disable People Federation Access Audit Tool 1.0. This toolkit covers aspects like ramps, door widths, signage, and accessible routes, also the noncompliance extends beyond physical structures to digital accessibility.

2. Facilities for Students with Disabilities:

- Classrooms did not have adjustable seating arrangements, clear sightlines, and adequate space for mobility aids also including accessible desks and adjustable podiums.
- Libraries require accessible shelving, reading stations, and assistive technology (such as screen readers) to enhance library usability.
- Restrooms (WASH facilities) are not wheelchair-accessible or have grab bars and sinks at an appropriate height.

3. Access to Classrooms, WASH Facilities, and Common Areas:

- Classrooms do not have wide doorways and ramps to ensure access to classrooms. Additionally, acoustics are not considered for students with hearing impairments.
- > WASH Facilities do not have accessible restrooms with proper signage and a clear pathway to the wash facilities.
- Common Areas like corridors and gathering spaces are not barrier-free and are without proper lighting and contrasting floor materials to aid navigation.

PROJECT NAME: PROJECT NUMBER: SCHOOL NAME: INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

22403058

DRAIBA PRIMARY SCHOOL



7) **SUMMARY OF FINDINGS**

The following summarizes the individual characteristics assessed during the Suva-Nausori school audit for Draiba Primary School:

Categories of	Existing Condition / State	Required as per Standards	Gaps Observed
Assessment	3		
Existing Infrastructure Condition	- Structural Integrity – Columns, slabs, beams, rafters, purlins of adequate size General upkeep – Minor irregular maintenance Safety compliance-handrails where necessary Disability- no consideration when constructed Ventilation and lighting – damaged and missing lights at some sections of buildings.	- Structural Integrity – Columns, slabs, beams, rafters, purlins sizes to follow FNBC 1990 General upkeep –routine checkup as per MOE policies with major defects requiring immediate intervention Safety compliance- handrails, extra doors and signage where necessary Disability- to comply with FDPF Disability audit tool - Ventilation and lighting – adequate windows and doors required as per FNBC 1990.	 Structural Integrity – Columns, slabs, beams, rafters, purlins sizes to follow FNBC 1990. General upkeep –requires immediate intervention to minor defects. Disability- not fully compliant with FDPF Disability audit tool Ventilation and lighting – limitations in the count of windows and lightings compared to required FNBC.
Assessment of Overcrowding	- The classrooms are accommodating an average of 770 roll/21 classrooms of 37 students.	- FNBC 1990 requires classroom occupancy to have 2m² per person. Based on that, the required roll per classroom was calculated.	 - 6/21 classrooms were accommodating more roll than required. - Given the recommended sizing (1.5m²), about 3 extra classrooms are required to address overcrowding in school.
Water Sanitation Hygiene (WASH) facilities	Toilets (students: Cubicle) - Boys – 37:1 - Girls – 25:1 Taps (students: tap) - Students – 23:1 - Menstrual hygiene bins were not found in any female cubicle/toilet	Toilets Ratio (students: Cubicle) - Boys – 30:1 - Girls – 20:1 Taps Ratio (students: tap) - Students – Please note: Above number of cubicles and taps are respective of 2024 enrolment numbers. Due to variation of ratio with student population in FNBC, the initial ratio is referred ONLY for reporting. - Menstrual hygiene bins to be present in every female washroom block	 The boys toilet ratio as well as the girl's toilet ratio is in par with the FNBC 1990 ratio. This may hinder later on with growing population. The tap ratio was in par with the FNBC indicating extra taps are not required in the school. The school requires maintenance of rusting pipes and algae buildup in WASH facilities.
Disaster Resilience Assessment	 Columns, beams, slabs had hairline cracks. All roof had truss roof frames. The windows only have mesh shutters at some sections. Roof cladding is rusted for some of the buildings. Roofing nails show rusting. 	Fiji Building Code 1990. Requirement is that roof cladding be free of rust and fastened securely with type 17 cyclonic screws with neoprene washers. Additionally, cyclone brackets to be fixed on every window frame.	 Rusting of cladding contradicts to the cyclone certification requirement requiring replacement. Absence of cyclone brackets are not acceptable as per the cyclone certification.

INFRASTRUCTURE ASSESSMENT FOR (DRAIBA PRIMARY SCHOOL)



Accessibility	- There are no handrails	The following are requirements from	The following facilities are missing.
Assessment	throughout the school	Fiji Disabled People's Federation	- Ramps and elevators for vertical access
	- Classrooms have typical	Access Audit Tool	- Wide doorways and clear pathways
	door size of 0.8 – 0.9m width.	- Ramps - required wherever elevation	- Proper signage
		with minimum 1:8 maximum 1:20	- Wheelchair-accessible restrooms
		- Walkway clearance -	- Grab bars
		- Handrails to be 0.76m to 0.9m.	- Proper signage
		- Doors and Door size – minimum 0.9m.	- Inclusive seating areas and pathways
		- Clearance required of 1.2m and tread	- Proper lighting
		width of minimum 310mm. (National	- Contrasting floor materials
		Building Code Table	- Handrails along the walkways.
		D2.1)	-

8) RECOMMENDATIONS

- In order to comply with the FNBC, the school will require the following:
 - Classrooms: An additional 8 new classrooms for students in years 4 6. This expansion aims to accommodate the growing number of students and provide them with an enhanced learning environment.
- WASH Facilities:
 - Since the boys' and girls' toilets is in par with the FNBC ratio, additional cubicles could be considered for future growing population, equipped with up-to-date WASH facilities catering particularly to disabled people. The exact number could be discussed upon further analysis.

Weekly routine maintenance work and daily cleanup directive from MOE is also a critical component of the plan which includes:

- Roof repairs due to rusting of cladding, roofing nails, gutter and gutter straps.
- Plumbing fixes due to algae buildup.
- New paint application on rails and walls

These maintenance activities are designed to address existing wear and tear and to ensure that the school buildings remain in good condition. It is recommended that maintenance be carried out at regular intervals, ideally every 12 months, to prevent deterioration and to maintain a safe and functional environment.

Accessibility: Prioritize building accessibility features, such as ramps and handrails, to ensure compliance with standards. These features are vital for providing all students, including those with disabilities, with equal access to the school's facilities.

9) COMPLIANCE

Upon inspecting Draiba Primary School, the following conclusions were drawn:

PROIFCT NAME: PROJECT NUMBER: 22403058 DRAIBA PRIMARY SCHOOL

SCHOOL NAME:

INFRASTRUCTURE ASSESSMENT FOR (DRAIBA PRIMARY SCHOOL)



- > MEHA Compliance: Compliant
- > WASH Facilities: The school has ample taps.
- > Land Availability: There is sufficient land for additional blocks.
- > NFA Compliance: Compliant with NFA basic guidelines but does not have NFA certification.
- **WAF Compliance:** Adequate water supply, but no backup system for water cuts.
- > FNBC Compliance: The school is not fully compliant with the occupancy requirements as well as the category 5 cyclone standards based on the windows and roofing requirements.
- NDMO Compliance: Targeting NFA and NBC compliance for safety.
- **EFL Compliance:** Assumed to be compliant with EFL standards.
- > DISABILITY Accessibility: non-compliant

10) APPENDIX

Appendix A – Draiba Primary School Site Inspection Report

Appendix B - Excel Scoring Sheet

Appendix C – Land Available for Expansion

PROJECT NAME: PROJECT NUMBER: 22403058 SCHOOL NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

DRAIBA PRIMARY SCHOOL

Appendix A - Site Inspection Report



INFRASTRUCTURE ASSESSMENT AUDIT FOR SUVA – NAUSORI URBAN SCHOOLS

INFRASTRUCTURE ASSESSMENT FOR SUVA DRAIBA PRIMARY SCHOOL (2324)
SITE INSPECTION REPORT







Table of Contents

List	t of	Abbreviations	3
1)		SCHOOL BACKGROUND	3
i	a)	Table 1: SCHOOL DETAILS	5
	b)	Table 2: SCHOOL ENROLMENT FIGURES	5
	c)	Table 3: 2024 CLASSROOM ENROLLMENT DETAILS	6
2)		SCHOOL SITE PLAN (DRONE IMAGERY OF SCHOOL)	7
3)		VISUAL INSPECTION RESULTS	8
	d)	BUILDING 1: EXISTING BUILDING INFORMATION	8
	e)	EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS \dots	9
	f)	BUILDING 2: EXISTING BUILDING INFORMATION	10
	g)	EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS	11
	h)	BUILDING 3: EXISTING BUILDING INFORMATION	12
	i)	EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS	13
	j)	TOILET BLOCK	14
	k)	BUILDING 4: EXISTING BUILDING INFORMATION	15
	I)	EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS \dots	16
	m)	TOILET BLOCK	17
	n)	BUILDING 5: EXISTING BUILDING INFORMATION	18
	o)	EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS	19
	p)	TOILET BLOCK	20
	q)	BUILDING 6: EXISTING BUILDING INFORMATION	21
	r)	EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS \dots	22
	s)	TOILET BLOCK	23
,	t)	BUILDING 7: EXISTING BUILDING INFORMATION	24
	u)	EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS	25
,	v)	BUILDING 8: EXISTING BUILDING INFORMATION	26
,	w)	EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS \dots	27
,	x)	TOILET BLOCK	28
,	y)	BUILDING 9: EXISTING BUILDING INFORMATION	29
;	z)	EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS \dots	30
i	aa)	BUILDING 10: EXISTING BUILDING INFORMATION	31
	bb)	EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS \dots	32
	cc)	BUILDING 11: EXISTING BUILDING INFORMATION	33
	dd)	EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS \dots	34
5.)		PHOTOGRAPHIC REPORT	35



List of Abbreviations									
NRW Macallan (Fiji) Pte Ltd									
Ministry of Education									
Tetra Tech International Development Pty Ltd									
Department of Foreign Affairs and Trade (Australia)									
Free Education Grant									
Occupational Health and Safety									
National Fire Authority									
Water Authority of Fiji									
National Building Code									
National Disaster Management Office									
Energy Fiji Limited									



Draiba Primary School, located in Suva, has a rich history tied to the legacy of Ratu Sir Lala Sukuna. The school was originally established in 1945 as Draiba Fijian Primary School to support the education of the iTaukei people. It has since evolved into a prominent educational institution in the region, known for its commitment to academic excellence and cultural heritage.

The school is situated on Ratu Sukuna Road and continues to play a significant role in the local community. Draiba Primary School has also served as an evacuation center during emergencies, highlighting its importance beyond just education.



Table 1: SCHOOL DETAILS

NAME OF SCHOOL SCHOOL REGISTRATION NUMBER SCHOOL LOCATION RATU SUKUNA ROAD, LAUCALA	
SCHOOL LOCATION RATU SUKUNA ROAD, LAUCALA	
SCHOOL TYPE PRIMARY SCHOOL	
FEEDER SCHOOL	
DATE OF INSPECTION 04 TH JULY, 2024	
MILESTONE (37 / 86 SCHOOLS)	
INSPECTED BY (TEAM 2) KUNAL NAND (KN)	
HENDRY TABULAWAKI (HT)	
CLIFFTON RAITAVOWAI (CR)	
MARIA LUTUA (ML)	

Table 2: SCHOOL ENROLMENT FIGURES

Year of	Numb	er of Studer	nts	Students	Number of	Number of Teachers		
Enrolment	Male	Female	Total	with Disability	Male	Female	Total	Comments
2024			758		6	15	21	21 Classrooms
2023			748		5	13	18	Student to stream average
2022			607		5	13	18	ratio is 48 :1 for 2024 school
2021			517		5	13	18	calendar.
2020			500		5	13	18	WASH ratio = 10: 1 per tap
			493				16	= 7: 1 per toilet
2019					5	11		Draiba Primary School is
								also an Evacuation Centre.




Table 3: 2024 CLASSROOM ENROLLMENT DETAILS

GRADE	CLASS	TOTAL	OM ENROLLN NUMBER OF	DIMENS		ACCESS V	VAY COUNT	OVERCROWDING
GRADE	NUMBER	STUDENT	TEACHERS	LENGTH	WIDTH	NO. OF	NO. OF	OVERGROWDING
	TIGNIBLIT	ROLL	12/torizito	LLIGIII	Wibiii	DOORS	WINDOWS	
1	101	47	1	9.3	6.6	1	10	⊠YES □NO
	102	44	1	9.3	6.6	2	8	⊠YES □NO
2	201	44	1	9.0	6.5	1	10	⊠YES □NO
	202	41	1	9.2	6.5	1	10	⊠YES □NO
3	301	44	1	9.2	5.7	1	10	⊠YES □NO
	302	45	1	9.2	5.7	1	10	⊠YES □NO
4	401	29	1	8.5	6.7	2	16	□YES ⊠NO
	402	30	1	7.0	6.5	2	21	□YES ⊠NO
	403	28	1	8.5	6.7	1	18	□YES ⊠NO
5	501	31	1	8.8	5.7	1	10	□YES ⊠NO
	502	25	1	8.8	5.7	1	10	□YES ⊠NO
	503	32	1	9.0	5.7	1	10	□YES ⊠NO
6	601	33	1	8.3	7.8	1	13	□YES ⊠NO
	602	30	1	8.5	6.1	2	12	□YES ⊠NO
	603	32	1	9.8	6.4	2	20	□YES ⊠NO
7	701	28	1	8.5	6.1	2	12	□YES ⊠NO
	702	31	1	8.5	6.1	2	12	□YES ⊠NO
	703	31	1	8.5	6.1	2	12	□YES ⊠NO
8	801	38	1	8.3	7.8	1	13	□YES ⊠NO
	802	40	1	8.3	7.8	1	13	□YES ⊠NO
	803	37	1	8.3	7.8	1	13	□YES ⊠NO



2) SCHOOL SITE PLAN (DRONE IMAGERY OF SCHOOL)





LEGEND									
B#	BUIDLINGS	DR#	PONDS/CREEKS/DRAINAGE						
PG#	PLAYGROUND	H#	HOSTELS						
WC#	TOILETS	ST#	STAFF QUARTERS						
T#	TAP / WASH AREA	F#	DINING/FOOD AREA						
WS#	WATER STORAGE FACILITY	EFL#	EFL POSTS/ JUNCTION BOX						
SEP#	SEPTIC TANK	CP	CAR PARK						
LA#	LAND AVAILABILITY	WW#	WALKWAY						

PROJECT NAME: PROJECT NUMBER: SCHOOL NAME: INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

22403058

DRAIBA PRIMARY SCHOOL



3) VISUAL INSPECTION RESULTS

BUILDING 1: EXISTING BUILDING INFORMATION

Building Index B1: Classrooms Year built: 2014 (Age: 10 years old)

Type: Single storey timber structure that consists of timber columns and beams with timber external walls and timber framed roof structure.

Dimensions Length (m): 34 Width (m): 10.1 Height (m): 2.8 (from eaves end)

Existing State of Building

REF. No.	Building Component	Good ¹	Fair ²	Poor ³	Structure Type ⁴		Comments
1	Roof Lining		✓		Steel		
2	Roof Structure		✓		Timber		
3	Walls		✓		Timber		
4	Columns		✓		Timber		
5	Beams		✓		Timber		
6	Floor		✓		Timber		
7	Handrails		✓		Timber & Steel		
8	Walkway(s)		√		Timber & Concrete		
9	Services – water supply		✓				
10	Available taps for general use		✓			9 taps	Student – tap ratio = 7: 1
11	Services – electricity		✓				
12	Services – communication (internet)		✓			Wireless Conne	ection
13	Drainage		✓				

Comments

- Lights and fans are functional.
- Cyclone mesh shutters at some locations only (one side of the wall).
- Two fire extinguishers present in the classroom but require maintenance.
- 280mm step to classroom.
- A sample classroom was chosen, the dimensions are as follows:
 - > Length (m): 8.4, Width (m): 7.9, Height (m): 2.35

PROJECT NAME: PROJECT NUMBER: INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

22403058

¹ Good - No additional works / intervention required

² Fair - Remedial works required – min CAT 3 standard

³ Poor - Demolition and replace with new - min CAT 4 standard

⁴ Type of structure - Timber/concrete/steel



EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS

Building Index B1 – Classrooms

Type: Single storey timber structure that consists of timber columns and beams with timber external walls

No. of Levels: 1

and timber framed roof structure.

Dimensions

Length (m):

Width (m): Height (m):

Existing State of Building

Existing State of Building										
REF. No.	Building Component	Good ⁵	Fair ⁶	Poor ⁷	Structure Type 8	Dimension s (m)	Comments			
1	Ramps			✓		N/A	No disability accessibility			
2	Walkway clearance space		✓		Timber & Concrete	1.8m Wide				
3	Handrails		√		Timber & Steel	900mm Height				
	Doors and Door Size (typical)		√		Timber	900mm Wide				
4	Stairway									
5										

Comments

- There are no toilets for this building.
- The school shall provide disability provisions if there is a demand to provide these provisions.

PROJECT NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

⁵ Good - No additional works / intervention required

⁶ Fair - Remedial works required – min CAT 3 standard

⁷ Poor - Demolition and replace with new - min CAT 4 standard

⁸ Type of structure - Timber/concrete/steel



BUILDING 2: EXISTING BUILDING INFORMATION

Building Inde	uilt: Unknown						
Type:	Type: Single storey concrete structure that consists of reinforced concrete columns and beams with masonry external walls and timber framed roof structure.						
Dimensions Length (m): 31.9 Width (m): 9.2 Height (m):					Height (m): 4.	.1	

Existing State of Building

Exiting State of Building												
REF. No.	Building Component	Good ⁹	Fair ¹⁰	Poor ¹¹	Structure Type ¹²	Comments						
1	Roof Lining		✓		Steel							
2	Roof Structure		✓		Timber							
3	Walls		✓		Masonry							
4	Columns		✓		Concrete							
5	Beams		✓		Concrete							
6	Floor		✓		Timber							
7	Handrails			✓		No Handrails						
8	Walkway(s)		✓		Concrete							
9	Services – water supply			✓								
10	Available taps for general use			✓		1 tap	Student – tap ratio = 10:1					
11	Services – electricity			✓		Only 1 light & no fan						
12	Services – communication (internet)		✓			Wireless Conne	ction					
13	Drainage		✓									

Comments

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor and walls.
- Surface cracks are visible along the column at some locations.
- No Fire Extinguishers available.
- No Fire hose reels installed along the veranda.
- No cyclone mesh shutters.
- Missing Louvers
- A sample classroom was chosen, the dimensions are as follows:
 - > Length (m): 9.0, Width (m): 5.8, Height (m): 3.1

PROJECT NAME: PROJECT NUMBER:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

22403058

⁹ Good - No additional works / intervention required

 $^{^{10}}$ Fair - Remedial works required – min CAT 3 standard

 $^{^{11}}$ Poor - Demolition and replace with new - min CAT 4 standard

 $^{^{\}rm 12}$ Type of structure - Timber/concrete/steel



EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS

Building Index	B2: Classrooms										
Type:	Type: Single storey concrete structure that consists of reinforced concrete columns and beams with masonry external walls and timber framed roof structure.										
Dimensions	Length (m):		Width (r	n):		Height (m):					
Existing State of Building											
REF. No.	Building Component	Good 13	Fair ¹⁴	Poor ¹⁵	Structure Type ¹⁶	Dimension s (m)	Comments				
1	Ramps			✓		N/A	No disability accessibility				
2	Walkway clearance space		✓		Concrete	3.0m Wide					
3	Handrails			✓		N/A	No Handrails				
	Doors and Door Size (typical)		✓			1.6m Wide					
4	Stairway	Stairway									
5											

Comments

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs & walls.
- There are no toilets for this building.
- No ramps only steep steps to the classrooms.
- The school shall provide disability provisions if there is a demand to provide these provisions.

PROJECT NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

¹³ Good - No additional works / intervention required

¹⁴ Fair - Remedial works required – min CAT 3 standard

¹⁵ Poor - Demolition and replace with new - min CAT 4 standard

¹⁶ Type of structure - Timber/concrete/steel



BUILDING 3: EXISTING BUILDING INFORMATION

Building Index B3: Toilet Block (for classes 6-8) Year built: Unknown

Type: Single storey concrete structure that consists of reinforced concrete columns and beams

No. of Levels: 1

with masonry external walls and timber framed roof structure.

Dimensions Length (m): 12.5 Width (m): 3.0 Height (m): 2.7 (from eaves end)

Existing State of Building

				oung otato	or building		
REF. No.	Building Component	Good ¹⁷	Fair ¹⁸	Poor ¹⁹	Structure Type ²⁰	Comments	
1	Roof Lining		✓		Steel		
2	Roof Structure		✓		Timber		
3	Walls		✓		Masonry		
4	Columns		✓		Concrete		
5	Beams		✓		Concrete		
6	Floor		✓		Concrete		
7	Handrails			✓		No Handrails	
8	Walkway(s)		✓		Concrete		
9	Services – water supply		✓				
10	Available taps for general use		✓			2 taps	Student – tap ratio = 20:1
11	Services – electricity		✓			All lights working	
12	Services – communication (internet)		✓			Wireless Connection	
13	Drainage		✓				

Comments

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor.
- Cracks are visible along the column at some locations.
- Rafter, wall plate & beam connection.

PROJECT NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

¹⁷ Good - No additional works / intervention required

¹⁸ Fair - Remedial works required – min CAT 3 standard

¹⁹ Poor - Demolition and replace with new - min CAT 4 standard

²⁰ Type of structure - Timber/concrete/steel



Height (m):

EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS

Building Index B3 – Toilet Block

Type: Single storey concrete structure that consists of reinforced concrete columns and beams with

No. of Levels: 1

masonry external walls and timber framed roof structure.

Dimensions Length (m): Width (m):

Existing State of Building

		EXISU	ing State	oi bulluli	ıy		
REF. No.	Building Component	Good 21	Fair ²²	Poor ²³	Structure Type ²⁴	Dimension s (m)	Comments
1	Ramps			✓		N/A	No disability accessibility
2	Walkway clearance space		✓		Concrete	1.2m Wide	
3	Handrails			✓		N/A	
	Doors and Door Size (typical)		✓		Timber	800mm Wide	
4	Stairway			✓	N/A	N/A	
5							

Comments

- Door Size is not wide enough. Does not meet disability accessibility requirements.
- The school shall provide disability provisions if there is a demand to provide these provisions.

PROJECT NAME: PROJECT NUMBER:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

22403058

 $^{^{\}rm 21}\,\mbox{Good}$ - No additional works / intervention required

²² Fair - Remedial works required - min CAT 3 standard

²³ Poor - Demolition and replace with new - min CAT 4 standard

²⁴ Type of structure - Timber/concrete/steel



TOILET BLOCK

Building Index	Building Index B3 – Toilet Block								
Туре:	Single storey concrete structure that consists of reinforced concrete columns and beams with masonry external walls and timber framed roof structure. No. of Levels: 1								
Dimensions	Length (m):	Width (m):	Height (r	leight (m):					
	Eviat	ting State of Building							

Existing State of Build	Existing	State	of I	Bui∣	lding	
-------------------------	----------	-------	------	------	-------	--

REF. No.	Building Component	Good ²⁵	Fair ²⁶	Poor ²⁷	Structure Type ²⁸	Count 29		Comments
1	Toilet Bays – male		✓			5	4 bays ar	nd 1 urinal
2	Toilet Bays – female		✓			5	5 bays	
3	Toilet Partition between boys and girls.		✓					
4	Shower bay		✓			2		in the female toilet ower in the male toilet
5	Toilet Bays – accessible		✓					
6	Entry to toilet building		✓			1		
7	Exit to toilet building		✓			1		
8	Menstrual Hygiene facilities		✓			1		
9	Students to WASH ratio	Toilet tap	s:	Male	#:1	F	emale	#: 1

Comments

• There are no Disability toilets for both male and female toilets

PROJECT NAME: INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

²⁵ Good - No additional works / intervention required

²⁶ Fair - Remedial works required – min CAT 3 standard

 $^{^{\}rm 27}$ Poor - Demolition and replace with new - min CAT 4 standard

²⁸ Type of structure - Timber/concrete/steel

²⁹ Count - Used for identifying number of toilet bays and menstrual hygiene facilities

Length (m): 24.1



BUILDING 4: EXISTING BUILDING INFORMATION

Building Index B4: Classrooms & Girls Toilet (for classes 1-4) Year built: Unknown

Type: Single storey concrete structure that consists of reinforced concrete columns and No. of Levels: 1

Width (m): 5.4

beams with masonry external walls and timber framed roof structure.

Height (m): 3.7 (from eaves end)

Existing State of Building

	Existing State of Building									
REF. No.	Building Component	Good ³⁰	Fair ³¹	Poor ³²	Structure Type ³³		Comments			
1	Roof Lining		✓		Steel					
2	Roof Structure		✓		Timber					
3	Walls		✓		Masonry					
4	Columns		✓		Concrete					
5	Beams		✓		Concrete					
6	Floor		✓		Timber					
7	Handrails			✓	N/A	No Handrails				
8	Walkway(s)		✓		Concrete					
9	Services – water supply		✓							
10	Available taps for general use		✓			6 taps	Student – tap ratio = 5:1			
11	Services – electricity			✓		Faulty Lights				
12	Services – communication (internet)		✓			Wireless Connection				
13	Drainage		✓							

Comments

Dimensions

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor and walls.
- No Fire Extinguishers available.
- No Fire hose reels installed along the veranda.
- Cyclone mesh shutters present on one side only.
- Damaged timber floors
- Leaking roof
- The timber is deteriorating
- A sample classroom was chosen, the dimensions are as follows:
 - Length (m): 9.25, Width (m): 6.7, Height (m): 3.2

PROJECT NAME: PROJECT NUMBER: INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

22403058

³⁰ Good - No additional works / intervention required

³¹ Fair - Remedial works required – min CAT 3 standard

³² Poor - Demolition and replace with new - min CAT 4 standard

³³ Type of structure - Timber/concrete/steel



Height (m):

EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS

Building Index B4 – Classrooms & Girls Toilet

Type: Single storey concrete structure that consists of reinforced concrete columns and beams with

No. of Levels: 1

masonry external walls and timber framed roof structure.

Dimensions Length (m): Width (m):

Existing State of Building

Existing State of Building										
REF. No.	Building Component	Good 34	Fair ³⁵	Poor ³⁶	Structure Type ³⁷	Dimension s (m)	Comments			
1	Ramps			✓		N/A	No disability accessibility			
2	Walkway clearance space		✓		Concrete	2.3m Wide				
3	Handrails			✓	N/A					
	Doors and Door Size (typical)		√		Timber	1.6m Wide				
4	Stairway				N/A	N/A				
5										

Comments

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor and walls.
- The school shall provide disability provisions if there is a demand to provide these provisions.

PROJECT NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

³⁴ Good - No additional works / intervention required

³⁵ Fair - Remedial works required – min CAT 3 standard

³⁶ Poor - Demolition and replace with new - min CAT 4 standard

³⁷ Type of structure - Timber/concrete/steel



TOILET BLOCK

Building Index	B4 – Female Toilet								
Type:	Single storey concrete structure that consists of reinforced concrete columns and beams with masonry external walls and timber framed roof structure. No. of Levels: 1								
Dimensions	Length (m):	Width (m):	Height (r	leight (m):					
		ing Ctata of Duilding							

Existing State of Building

DEE N.	Dullella a Octobra	A 120	F-1-20	D40	04	01		0 1 -
REF. No.	Building Component	Good ³⁸	Fair ³⁹	Poor ⁴⁰	Structure Type 41	Count 42		Comments
1	Toilet Bays – male			✓		N/A	No boy'	s toilet
2	Toilet Bays – female		✓			7	7 bays	
3	Toilet Partition between boys and girls.							
4	Shower bay		✓			4		
5	Toilet Bays – accessible		✓					
6	Entry to toilet building		✓			1		
7	Exit to toilet building		✓			1		
8	Menstrual Hygiene facilities			✓		0		
9	Students to WASH ratio	Toilet tap	s:	Male	5:1	Fe	male	5:1

Comments

- There was no menstrual bin in the female toilet, instead there was a rubbish bin present.
- There are no Disability toilets for the female toilets.

PROJECT NAME: INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

³⁸ Good - No additional works / intervention required

³⁹ Fair - Remedial works required – min CAT 3 standard

 $^{^{\}rm 40}$ Poor - Demolition and replace with new - min CAT 4 standard

⁴¹ Type of structure - Timber/concrete/steel

 $^{^{\}rm 42}$ Count - Used for identifying number of toilet bays and menstrual hygiene facilities



BUILDING 5: EXISTING BUILDING INFORMATION

Building Index B5: Classrooms, Storage & Staff Toilets Year built: Unknown

Single storey concrete structure that consists of reinforced concrete columns and beams

No. of Levels: 1

with masonry external walls and timber framed roof structure.

Dimensions Length (m): 28.5 Width (m): 9.1 Height (m): 3.6 (from eaves end)

Existing State of Building

REF. No.	Building Component	Good ⁴³	Fair ⁴⁴	Poor ⁴⁵	Structure Type ⁴⁶	Comments		
1	Roof Lining		✓		Steel	Could not be accessed	during the inspection.	
2	Roof Structure		✓		Timber			
3	Walls		✓		Masonry			
4	Columns		✓		Concrete			
5	Beams		✓		Concrete			
6	Floor		✓		Concrete			
7	Handrails			✓	N/A	No Handrails		
8	Walkway(s)		✓		Concrete			
9	Services – water supply		✓					
10	Available taps for general use		√			10 taps	Student – tap ratio = 5:1	
11	Services – electricity			✓		No working lights nor fa	ans	
12	Services – communication (internet)		√			Wireless Connection		
13	Drainage		✓					

Comments

Type:

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor.
- Leaking roof
- Cyclone mesh shutters at some locations only.
- There were no Fire extinguishers available.
- A sample classroom was chosen, the dimensions are as follows:
 - > Length (m): 8.9, Width (m): 6.5, Height (m): 3.1

⁴³ Good - No additional works / intervention required

PROJECT NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

 $^{^{\}rm 44}$ Fair - Remedial works required – min CAT 3 standard

 $^{^{45}}$ Poor - Demolition and replace with new - min CAT 4 standard

⁴⁶ Type of structure - Timber/concrete/steel



Height (m):

EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS

Building Index B5 – Classrooms, Storage & Staff Toilets

Type: Single storey concrete structure that consists of reinforced concrete columns and beams with

No. of Levels: 1

masonry external walls and timber framed roof structure.

Dimensions Length (m): Width (m):

Existing State of Building

Existing State of Building										
REF. No.	Building Component	Good 47	Fair ⁴⁸	Poor ⁴⁹	Structure Type ⁵⁰	Dimension s (m)	Comments			
1	Ramps			✓		N/A	No disability accessibility			
2	Walkway clearance space		✓		Concrete	2.1m Wide				
3	Handrails			✓	N/A					
	Doors and Door Size (typical)		✓		Timber	1.5m Wide				
4	Stairway			✓	N/A	N/A				
5										

Comments

• The school shall provide disability provisions if there is a demand to provide these provisions.

PROJECT NAME: PROJECT NUMBER:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

22403058

⁴⁷ Good - No additional works / intervention required

⁴⁸ Fair - Remedial works required – min CAT 3 standard

⁴⁹ Poor - Demolition and replace with new - min CAT 4 standard

⁵⁰ Type of structure - Timber/concrete/steel



TOILET BLOCK

Building Index	B5 – Staff Toilets								
Type:	Single storey concrete structure that consists of reinforced concrete columns and beams with masonry external walls and timber framed roof structure. No. of Levels: 1								
Dimensions	Length (m):	Width (m):	Height (r	leight (m):					
	F!-a	ling Ctata of Duilding							

Existing State of Building

REF. No.	Building Component	Good ⁵¹	Fair ⁵²	Poor ⁵³	Structure Type ⁵⁴	Coun 55	nt	Comments
1	Toilet Bays – male		✓			1		
2	Toilet Bays – female		✓			1		
3	Toilet Partition between boys and girls.							
4	Shower bay			✓		0		
5	Toilet Bays – accessible		✓					
6	Entry to toilet building		✓			1		
7	Exit to toilet building		✓			1		
8	Menstrual Hygiene facilities		✓			1		
9	Students to WASH ratio	Toilet tap	s:	Male	5:1		Female	5:1

Comments

- There was a rubbish bin present in both male and female staff toilet.
- There are no Disability toilets for the female toilets.

PROJECT NAME: INFRASTRU PROJECT NUMBER: 22403058

⁵¹ Good - No additional works / intervention required

⁵² Fair - Remedial works required – min CAT 3 standard

 $^{^{\}rm 53}$ Poor - Demolition and replace with new - min CAT 4 standard

⁵⁴ Type of structure - Timber/concrete/steel

 $^{^{55}}$ Count - Used for identifying number of toilet bays and menstrual hygiene facilities



BUILDING 6: EXISTING BUILDING INFORMATION

Building Index B6: Classrooms & Boys Toilet (for classes 1-4) Year built: Unknown

Single storey concrete structure that consists of reinforced concrete columns and beams

No. of Levels: 1

with masonry external walls and timber framed roof structure.

Dimensions Length (m): 24.3 Width (m): 9.1 Height (m): 3.7 (from eaves end)

Existing State of Building

	5								
REF. No.	Building Component	Good ⁵⁶	Fair ⁵⁷	Poor ⁵⁸	Structure Type ⁵⁹	Comments			
1	Roof Lining		✓		Steel	Could not be accessed during the inspection.			
2	Roof Structure		✓		Timber				
3	Walls		✓		Masonry				
4	Columns		✓		Concrete				
5	Beams		✓		Concrete				
6	Floor		✓		Timber				
7	Handrails			✓	N/A	No Handrails			
8	Walkway(s)		✓		Concrete				
9	Services – water supply		✓						
10	Available taps for general use		√			0 taps Student – tap ratio			
11	Services – electricity			✓		Faulty lights			
12	Services – communication (internet)		✓			Wireless Connection			
13	Drainage		✓						

Comments

Type:

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor and walls.
- Cyclone mesh shutters at one side only.
- · Ceiling and timber floor are sagging.
- There were no Fire extinguishers available.
- A sample classroom was chosen, the dimensions are as follows:
 - > Length (m): 9.1, Width (m): 6.8, Height (m): 3.2

PROJECT NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

⁵⁶ Good - No additional works / intervention required

⁵⁷ Fair - Remedial works required – min CAT 3 standard

 $^{^{58}}$ Poor - Demolition and replace with new - min CAT 4 standard

⁵⁹ Type of structure - Timber/concrete/steel



Height (m):

EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS

Building Index B6: Classrooms & Boys Toilet (for classes 1-4)

Type: Single storey concrete structure that consists of reinforced concrete columns and beams with

No. of Levels: 1

masonry external walls and timber framed roof structure.

Dimensions Length (m): Width (m):

Existing State of Building

REF. No.	Building Component	Good 60	Fair ⁶¹	Poor ⁶²	Structure Type ⁶³	Dimension s (m)	Comments
1	Ramps			✓		N/A	No disability accessibility
2	Walkway clearance space		✓		Concrete	2.1m Wide	
3	Handrails			✓	N/A		
	Doors and Door Size (typical)		✓		Timber	1.5m Wide	
4	Stairway			✓	N/A	N/A	
5							

Comments

• The school shall provide disability provisions if there is a demand to provide these provisions.

PROJECT NAME: PROJECT NUMBER:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

22403058

⁶⁰ Good - No additional works / intervention required

⁶¹ Fair - Remedial works required – min CAT 3 standard

 $^{^{62}}$ Poor - Demolition and replace with new - min CAT 4 standard

⁶³ Type of structure - Timber/concrete/steel



TOILET BLOCK

Building Index	B6 – Classrooms & Boys Toilet (for classes 1-4)						
Type:	Single storey concrete structure that and beams with masonry external was		No. of Levels: 1				
Dimensions	Length (m):	Width (m):	Height (n	t (m):			

Existing State of Building

Existing state of building								
REF. No.	Building Component	Good ⁶⁴	Fair ⁶⁵	Poor ⁶⁶	Structure Type ⁶⁷	Count 68		Comments
1	Toilet Bays – male		✓			7	4 bays &	3 urinals
2	Toilet Bays – female			✓		N/A		
3	Toilet Partition between boys and girls.							
4	Shower bay		✓			6		
5	Toilet Bays – accessible		√					
6	Entry to toilet building		✓			1		
7	Exit to toilet building		✓			1		
8	Menstrual Hygiene facilities			✓		N/A		
9	Students to WASH ratio	Toilet tap	s:	Male	5:1	F	emale	5:1

Comments

- There's no door to the toilet.
- There are no disability toilets for the boy's toilets.

PROJECT NAME: INFRASTRU PROJECT NUMBER: 22403058

⁶⁴ Good - No additional works / intervention required

⁶⁵ Fair - Remedial works required – min CAT 3 standard

 $^{^{\}rm 66}$ Poor - Demolition and replace with new - min CAT 4 standard

⁶⁷ Type of structure - Timber/concrete/steel

⁶⁸ Count - Used for identifying number of toilet bays and menstrual hygiene facilities



BUILDING 7: EXISTING BUILDING INFORMATION

Building Index B7: Classrooms Year built: Unknown

Single storey timber structure that consists of timber columns and beams with timber Type: external walls and timber framed roof structure.

No. of Levels: 1

Dimensions Length (m): 17.6 Width (m): 9.5 Height (m): 4.0 (from eaves end)

Existing State of Building

	5												
REF. No.	Building Component	Good ⁶⁹	Fair ⁷⁰	Poor ⁷¹	Structure Type ⁷²	Comments							
1	Roof Lining		✓		Steel	Could not be accessed	during the inspection.						
2	Roof Structure		✓		Timber								
3	Walls		✓		Timber								
4	Columns		✓		Timber								
5	Beams		✓		Timber								
6	Floor		✓		Timber								
7	Handrails		✓		Timber								
8	Walkway(s)		✓		Concrete								
9	Services – water supply			✓									
10	Available taps for general use			✓		tap	Student – tap ratio = #: 1						
11	Services – electricity			✓		Lights are not working							
12	Services – communication (internet)		✓			Wireless Connection							
13	Drainage		✓										

Comments

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor and stairs.
- Cyclone mesh shutters present at one side only.
- Raking ceiling.
- Timber floor beam deteriorated.
- There were no Fire extinguishers available.
- A sample classroom was chosen, the dimensions are as follows:
 - > Length (m): 8.5, Width (m): 6.8, Height (m): 2.7

⁶⁹ Good - No additional works / intervention required

 $^{^{70}\,\}mbox{Fair}$ - Remedial works required – min CAT 3 standard

 $^{^{71}}$ Poor - Demolition and replace with new - min CAT 4 standard

⁷² Type of structure - Timber/concrete/steel



EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS

Building Index B7 – Classrooms

Type: Single storey timber structure that consists of timber columns and beams with timber external

No. of Levels: 1

walls and timber framed roof structure.

Dimensions Length (m): Width (m): Height (m):

Existing State of Building

Existing State of Building											
REF. No.	Building Component	Good 73	Fair ⁷⁴	Poor ⁷⁵	Structure Type ⁷⁶	Dimension s (m)	Comments				
1	Ramps			✓		N/A	No disability accessibility				
2	Walkway clearance space		✓		Concrete	2.3m Wide					
3	Handrails		✓		Timber	1.1m Height					
	Doors and Door Size (typical)		√		Timber	1.2m Wide					
4	Stairway			✓	N/A	N/A					
5											

Comments

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor.
- The school shall provide disability provisions if there is a demand to provide these provisions.

PROJECT NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058 SCHOOL NAME: DRAIBA PI

DRAIBA PRIMARY SCHOOL

 $^{^{73}}$ Good - No additional works / intervention required

 $^{^{74}\,\}mbox{Fair}$ - Remedial works required – min CAT 3 standard

⁷⁵ Poor - Demolition and replace with new - min CAT 4 standard

⁷⁶ Type of structure - Timber/concrete/steel



BUILDING 8: EXISTING BUILDING INFORMATION

Building Index B8: Toilet Block Year built: Unknown

Type: Single storey timber structure that consists of timber columns and beams with timber No. of Levels: 1

external walls and timber framed roof structure.

Length (m): 3.2 Width (m): 2.6 Height (m): 2.5 (from eaves end)

Existing State of Building

REF. No.	Building Component	Good ⁷⁷	Fair ⁷⁸	Poor ⁷⁹	Structure Type 80	Comments						
1	Roof Lining		✓		Steel	Could not be access	sed during the inspection.					
2	Roof Structure		✓		Timber							
3	Walls		✓		Timber							
4	Columns		✓		Timber							
5	Beams		✓		Timber							
6	Floor		✓		Concrete							
7	Handrails			✓	N/A	No Handrails						
8	Walkway(s)			✓								
9	Services – water supply		✓									
10	Available taps for general use		✓			1 tap	Student – tap ratio = 10:1					
11	Services – electricity		✓									
12	Services – communication (internet)		✓			Wireless Connection	1					
13	Drainage		✓									

Comments

Dimensions

Surface cracks (i.e. hairline cracks) are visible along the floor slabs.

PROJECT NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

⁷⁷ Good - No additional works / intervention required

⁷⁸ Fair - Remedial works required – min CAT 3 standard

⁷⁹ Poor - Demolition and replace with new - min CAT 4 standard

⁸⁰ Type of structure - Timber/concrete/steel



EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS

Building Index B8 – Toilet Block

Type: Single storey timber structure that consists of timber columns and beams with timber external

No. of Levels: 1

walls and timber framed roof structure.

Dimensions Length (m): Width (m): Height (m):

Existing State of Building

=Aloung out of Funding											
REF. No.	Building Component	Good 81	Fair ⁸²	Poor ⁸³	Structure Type 84	Dimension s (m)	Comments				
1	Ramps			✓		N/A	No disability accessibility				
2	Walkway clearance space			✓	N/A						
3	Handrails			✓	N/A						
	Doors and Door Size (typical)			✓	N/A						
4	Stairway				N/A	N/A					
5											

Comments

- No disability toilet.
- The school shall provide disability provisions if there is a demand to provide these provisions.

PROJECT NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

 $^{^{\}rm 81}\,\mbox{Good}$ - No additional works / intervention required

⁸² Fair - Remedial works required – min CAT 3 standard

⁸³ Poor - Demolition and replace with new - min CAT 4 standard

⁸⁴ Type of structure - Timber/concrete/steel



TOILET BLOCK

Building Index	B8 – Toilet Block									
Type:	Single storey timber structure that consists of timber columns and beams with timber external walls and timber framed roof structure. No. of Levels: 1									
Dimensions Length (m): Width (m): Height (m):										
Existing State of Building										

Existing State of Building

REF. No.	Building Component	Good ⁸⁵	Fair ⁸⁶	Poor ⁸⁷	Structure Type 88	Cour 89	nt	Comments
1	Toilet Bays – male		✓			1	1 bay 8	& no urinal
2	Toilet Bays – female		✓			1		
3	Toilet Partition between boys and girls.		✓					
4	Shower bay			✓		0		
5	Toilet Bays – accessible		√					
6	Entry to toilet building		√			1		
7	Exit to toilet building		✓			1		
8	Menstrual Hygiene facilities			✓		N/A		
9	Students to WASH ratio	Toilet tap	s:	Male	5:1		Female	5:1

Comments

- There was 1 shared wash basin.
- There are no disability toilets.

PROJECT NAME: INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS PROJECT NUMBER: 22403058

⁸⁵ Good - No additional works / intervention required

⁸⁶ Fair - Remedial works required – min CAT 3 standard

⁸⁷ Poor - Demolition and replace with new - min CAT 4 standard

⁸⁸ Type of structure - Timber/concrete/steel

⁸⁹ Count - Used for identifying number of toilet bays and menstrual hygiene facilities



BUILDING 9: EXISTING BUILDING INFORMATION

Building Index B9: Classrooms, Office & Library Year built: Unknown

Type: Single storey concrete structure that consists of reinforced concrete and steel columns and No. of Levels: 2

Width (m): 12.5

beams with masonry external walls and timber framed roof structure.

Height (m): 5.4 (from eaves end)

Existing State of Building

	Existing State of Building											
REF. No.	Building Component	Good ⁹⁰	Fair ⁹¹	Poor ⁹²	Structure Type ⁹³	Co	omments					
1	Roof Lining		✓		Steel	Could not be accesse	d during the inspection.					
2	Roof Structure		✓		Timber							
3	Walls		✓		Masonry							
4	Columns		✓		Concrete & Steel							
5	Beams		√		Concrete & Steel							
6	Floor		✓		Concrete							
7	Handrails			✓	Steel							
8	Walkway(s)		✓		Concrete							
9	Services – water supply			✓								
10	Available taps for general use			✓		0 tap	Student – tap ratio = #: 1					
11	Services – electricity		✓			Lights, aircon and fans are working						
12	Services – communication (internet)		√			Wireless Connection						
13	Drainage		✓									

Comments

Dimensions

Length (m): 19

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor.
- Cracks are visible on the walls at some locations.
- No cyclone mesh shutters.
- Damaged & rusted Handrails.
- No fire extinguishers
- No fire hose reel installed along the veranda.
- A sample classroom was chosen, the dimensions are as follows:
 - > Length (m): 7.0, Width (m): 6.3, Height (m): 2.7
 - Computer Lab Length (m): 6.9, Width (m): 6.2, Height (m): 2.85

PROJECT NAME: PROJECT NUMBER:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

22403058

⁹⁰ Good - No additional works / intervention required

⁹¹ Fair - Remedial works required – min CAT 3 standard

⁹² Poor - Demolition and replace with new - min CAT 4 standard

⁹³ Type of structure - Timber/concrete/steel



Height (m):

EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS

Building Index B9 – Classrooms, Office & Library

Type: Single storey concrete structure that consists of reinforced concrete and steel columns and

No. of Levels: 2

beams with masonry external walls and timber framed roof structure.

Dimensions

Length (m):

Width (m):

Existing State of Building

Existing State of Building											
REF. No.	Building Component	Good 94	Fair ⁹⁵	Poor ⁹⁶	Structure Type 97	Dimension s (m)	Comments				
1	Ramps			✓		N/A	No disability accessibility				
2	Walkway clearance space		✓		Concrete	2.5m Wide					
3	Handrails			✓	Steel	1.1m Height	Damaged & rusted				
	Doors and Door Size (typical)		√		Timber	800mm Wide					
4	Stairway		✓		Concrete	N/A					
5											

Comments

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor.
- Door Size is not wide enough. Does not meet disability accessibility requirements.
- The school shall provide disability provisions if there is a demand to provide these provisions.

PROJECT NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

⁹⁴ Good - No additional works / intervention required

 $^{^{\}rm 95}$ Fair - Remedial works required – min CAT 3 standard

⁹⁶ Poor - Demolition and replace with new - min CAT 4 standard

⁹⁷ Type of structure - Timber/concrete/steel



BUILDING 10: EXISTING BUILDING INFORMATION

Building Index B10: Classrooms Year built: Unknown

Type: Single storey timber structure that consists of timber columns and beams with timber No. of Levels: 1

external walls and timber framed roof structure.

Length (m): 10.2

Width (m): 10.6 Height (m): 4.0 (from eaves end)

Existing State of Building

REF.	Building Component	Good ⁹⁸	Fair ⁹⁹	Poor ¹⁰⁰	Structure Type ¹⁰¹	Comments	
1	Roof Lining		√		Steel	Could not be see	essed during the inspection.
			✓			Could flot be acc	essed during the inspection.
2	Roof Structure				Timber		
3	Walls		✓		Timber		
4	Columns		✓		Timber		
5	Beams		✓		Timber		
6	Floor		✓		Timber		
7	Handrails			✓	N/A		
8	Walkway(s)		✓		Concrete		
9	Services – water supply			✓			
10	Available taps for general use			√		0 tap	Student – tap ratio = #: 1
11	Services – electricity			✓		Faulty Lights	
12	Services – communication (internet)		√			Wireless Connection	
13	Drainage		✓				

Comments

Dimensions

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor.
- No cyclone mesh shutters.
- Not all the lights were working.
- Missing louvers.
- No fire extinguishers
- A sample classroom was chosen, the dimensions are as follows:
 - > Length (m): 9.6, Width (m): 6.3, Height (m): 2.7

PROJECT NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

⁹⁸ Good - No additional works / intervention required

⁹⁹ Fair - Remedial works required – min CAT 3 standard

¹⁰⁰ Poor - Demolition and replace with new - min CAT 4 standard

¹⁰¹ Type of structure - Timber/concrete/steel



EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS

Building Index B10 - Classrooms

Single storey timber structure that consists of timber columns and beams with timber external Type:

No. of Levels: 1

walls and timber framed roof structure.

Dimensions Length (m): Width (m): Height (m):

Existing State of Building

Existing State of Dunding											
REF. No.	Building Component	Good 102	Fair ¹⁰³	Poor 104	Structure Type 105	Dimension s (m)	Comments				
1	Ramps			✓		N/A	No disability accessibility				
2	Walkway clearance space		✓		Concrete	1.8m Wide					
3	Handrails			✓		N/A					
	Doors and Door Size (typical)		√		Timber	750mm Wide					
4	Stairway					N/A					
5											

Comments

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor.
- Door Size is not wide enough. Does not meet disability accessibility requirements.
- The school shall provide disability provisions if there is a demand to provide these provisions.

¹⁰² Good - No additional works / intervention required

 $^{^{103}}$ Fair - Remedial works required – min CAT 3 standard

 $^{^{104}}$ Poor - Demolition and replace with new - min CAT 4 standard

¹⁰⁵ Type of structure - Timber/concrete/steel



BUILDING 11: EXISTING BUILDING INFORMATION

Building Index B11: Classrooms Year built: Unknown

Type: Single storey timber structure that consists of timber columns and beams with timber external walls and timber framed roof structure.

Dimensions Length (m): 34.6 Width (m): 9.9 Height (m): 3.5 (from eaves end)

Existing State of Building

REF. No.	Building Component	Good 106	Fair ¹⁰⁷	Poor ¹⁰⁸	Structure Type ¹⁰⁹	Comments			
1	Roof Lining		✓		Steel	Could not be accessed	during the inspection.		
2	Roof Structure		✓		Timber				
3	Walls		✓		Timber				
4	Columns		✓		Timber				
5	Beams		✓		Timber				
6	Floor		✓		Timber				
7	Handrails			✓	N/A				
8	Walkway(s)		✓		Concrete				
9	Services – water supply		✓						
10	Available taps for general use		√			10 taps	Student – tap ratio = #: 1		
11	Services – electricity		✓						
12	Services – communication (internet)		√			Wireless Connection			
13	Drainage		✓						

Comments

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor.
- Cyclone mesh shutters present.
- Timber was deteriorating
- Sagging floors & ceiling
- No fire extinguishers
- A sample classroom was chosen, the dimensions are as follows:
 - > Length (m): 8.3, Width (m): 6.7, Height (m): 2.5

PROJECT NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

PROJECT NUMBER: 22403058

 $^{^{106}}$ Good - No additional works / intervention required

 $^{^{\}rm 107}$ Fair - Remedial works required – min CAT 3 standard

 $^{^{\}mbox{\scriptsize 108}}$ Poor - Demolition and replace with new - min CAT 4 standard

 $^{^{\}mbox{\scriptsize 109}}$ Type of structure - Timber/concrete/steel



EXISTING BUILDING AND TOILET BLOCKS ACESS INFORMATION FOR DISABILITY AUDITS

Building Index B11 - Classrooms

Single storey timber structure that consists of timber columns and beams with timber external Type:

No. of Levels: 1

walls and timber framed roof structure.

Dimensions Length (m): Width (m): Height (m):

Existing State of Building

	Existing state of building												
REF. No.	Building Component	Good 110	Fair ¹¹¹	Poor 112	Structure Type 113	Dimension s (m)	Comments						
1	Ramps			✓		N/A	No disability accessibility						
2	Walkway clearance space		✓		Concrete	2.9m Wide							
3	Handrails			✓		N/A							
	Doors and Door Size (typical)		√		Timber	750mm Wide							
4	Stairway					N/A							
5													

Comments

- Surface cracks (i.e. hairline cracks) are visible along the floor slabs along the corridor.
- Door size is not wide enough. Does not meet disability accessibility requirements.
- The school shall provide disability provisions if there is a demand to provide these provisions.

¹¹⁰ Good - No additional works / intervention required

 $^{^{111}}$ Fair - Remedial works required – min CAT 3 standard

 $^{^{112}}$ Poor - Demolition and replace with new - min CAT 4 standard


¹¹³ Type of structure - Timber/concrete/steel



5.) PHOTOGRAPHIC REPORT

Client:	TETRA TECH INTERNATIONAL DEVELOPMENT (PTY) LTD	School Name:	DRAIBA PRIMARY SCHOOL		
Project:	INFRASTRUCTURE PLAN FOR SUVA – NAUSORI URBAN SCHOOL.	Building Index:	B1		
	PHOTOGRAPH No. 1: FRONT	Pl	HOTOGRAPH No. 2: LEFT SIDE		
		W. Carlotte			
	PHOTOGRAPH No. 3: BACK	PH	IOTOGRAPH No. 4: RIGHT SIDE		





PHOTOGRAPH NO 7 - TOILETS



Client:	TETRA TECH INTERNATIONAL DEVELOPMENT (PTY) LTD	School Name:	DRAIBA PRIMARY SCHOOL
Project:	INFRASTRUCTURE PLAN FOR SUVA – NAUSORI URBAN SCHOOL.	Building Index:	B2
	PHOTOGRAPH No. 1: FRONT	Pł	HOTOGRAPH No. 2: LEFT SIDE
		T.C.	
	PHOTOGRAPH No. 3: BACK	PH	IOTOGRAPH No. 4: RIGHT SIDE
	THO TO OTHER THOU OF DITOR		





PHOTOGRAPH No. 5: INTERIOR


• There were no toilet bays for the building.

PHOTOGRAPH No. 6: ROOF SPACE



PHOTOGRAPH NO 7 - TOILETS

















PHOTOGRAPH No. 5: INTERIOR

PHOTOGRAPH No. 6: ROOF SPACE




PHOTOGRAPH NO 7 - TOILETS



Client:	TETRA TECH INTERNATIONAL DEVELOPMENT (PTY) LTD	School Name: DRAIBA PRIMARY SCHOOL
Project:	INFRASTRUCTURE PLAN FOR SUVA – NAUSORI URBAN SCHOOL.	Building Index: B5
SHE LONG	NNOTES BUT ON MILE SUPPLIES OF THE STREET OF	
		THE PARTY OF THE P
	PHOTOGRAPH No. 1: FRONT	PHOTOGRAPH No. 2: LEFT SIDE
	PHOTOGRAPH No. 3: BACK	PHOTOGRAPH No. 4: RIGHT SIDE







Client:	TETRA TECH INTERNATIONAL DEVELOPMENT (PTY) LTD	School Name:	DRAIBA PRIMARY SCHOOL
Project:	INFRASTRUCTURE PLAN FOR SUVA – NAUSORI URBAN SCHOOL.	Building Index:	B6
			PAIDA DDIMARY SCHOOL
			PRIMARY SEC MI-222+ EST 997 1900 Sulana Rd. PRIMARY EMICUL studies lefter a school Gyptions cont PRICAT: 3315030
	PHOTOGRAPH No. 1: FRONT	Pl	HOTOGRAPH No. 2: LEFT SIDE
1			
Jêz-			
	PHOTOGRAPH No. 3: BACK	PH	OTOGRAPH No. 4: RIGHT SIDE





PHOTOGRAPH No. 5: INTERIOR

PHOTOGRAPH No. 6: ROOF SPACE



PHOTOGRAPH NO 7 - TOILETS

PHOTOGRAPH NO 8 - TAPS

PROJECT NAME:
PROJECT NUMBER:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

22403058



Client:	TETRA TECH INTERNATIONAL DEVELOPMENT (PTY) LTD	School Name: DRAIBA PRIMARY SCHOOL
Project:	INFRASTRUCTURE PLAN FOR SUVA – NAUSORI URBAN SCHOOL.	Building Index: B7
	PHOTOGRAPH No. 1: FRONT	PHOTOGRAPH No. 2: LEFT SIDE
	THO TO SIGN THOS. 1. THOM	
	PHOTOGRAPH No. 3: BACK	PHOTOGRAPH No. 4: RIGHT SIDE





PHOTOGRAPH No. 5: INTERIOR	PHOTOGRAPH No. 6: ROOF SPACE		
There were no toilet bays for the building.	No taps available		
PHOTOGRAPH NO 7 - TOILETS	PHOTOGRAPH NO 8 - TAPS		

PROJECT NAME: PROJECT NUMBER: 22403058 SCHOOL NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

DRAIBA PRIMARY SCHOOL









PHOTOGRAPH No. 5: INTERIOR




PHOTOGRAPH No. 6: ROOF SPACE



PHOTOGRAPH NO 7 - TOILETS










PHOTOGRAPH No. 5: INTERIOR	PHOTOGRAPH No. 6: ROOF SPACE
There were no toilet bays for the building.	No taps available
PHOTOGRAPH NO 7 - TOILETS	PHOTOGRAPH NO 8 - TAPS

PROJECT NAME: PROJECT NUMBER: 22403058 SCHOOL NAME:

INFRASTRUCTURE PLAN FOR SUVA NAUSORI URBAN SCHOOLS

DRAIBA PRIMARY SCHOOL









PHOTOGRAPH No. 5: INTERIOR	PHOTOGRAPH No. 6: ROOF SPACE
There were no toilet bays for the building.	No taps available.
PHOTOGRAPH NO 7 - TOILETS	PHOTOGRAPH NO 8 - TAPS









PHOTOGRAPH No. 5: INTERIOR

• There were no toilet bays for the building.

PHOTOGRAPH No. 6: ROOF SPACE



PHOTOGRAPH NO 7 - TOILETS

Appendix B – Excel Scoring Sheet

	WEIGHTED CRITERIA		
1	PART A - CLASSROOM OVERCROWDING (40%) Classrooms facilitating students beyond room capacity, determined through number of students per classroom and classroom size		
	Fair - some classrooms are accommodating students above capacity.	24 to 31	31
	Criteria Item Score		31.0
2	PART B - WASH FACILITIES (20%) WASH- Student ratio based on the Fiji National Building Code (FNBC) Infrastructure Standards (10%)		
	Fair - WASH-Student ratio for school toilet blocks slightly falls below the ratio in the standard specified by FNBC.	6 to 7.9	7
2.1	Quality of facilities and current condition such as funtionality and maintenance (10%)		
	Poor - school toilet facilities are not maintained and the physical infrastructure cause major disturbances to end users.	8 to 10	8
	Criteria Item Score		15.0
3	PART C - CONDITION OF INFRASTRUCTURE (20%) Building structure and condition of walls, floors, ceilings, overall structural integrity (10%)		
	Poor - all building structures need remedial work to improve structural integrity and condition.	8 to 10	8
3.1	Maintenance and assessment of the upkeep of facilities including painting and repairs (10%)		
	Poor - school facilities are not maintained and the physical infrastructure cause major disturbances to end users.	8 to 10	8
	Criteria Item Score		16.0
	PART D - DISABILITY ACCESSIBILITY (10%)		
4	Accessibility features such as the presence of existing ramps, handrails, accessible toilets etc		
	Poor - School buildings and facilities do not have accessibility features.	8 to 10	10
	Criteria Item Score		10.0
	PART E - DISASTER RESILIENCE (10%)		
5	Presence and quality of measures for disaster resilience of buildings including structural measures, cyclone shutters and fire safety systems		
	Fair - some school building structures are not resilient to natural disasters and do not have safety systems in place.	6 to 7.9	6
	Criteria Item Score		6.0
	TOTAL CRITERIA SCORE		78.0

Appendix C – Land Available for Expansion













NRW MACALLAN (FIJI) LTD CONSULTING ENGINEERS

CIVIL, STRUCTURAL, ELECTRICAL, MECHANICAL & PROJECT MAMAGEMENT 79 RATU MARA ROAD, SAMABULA, SUVA.
P O BOX 1208, SUVA. PHONE: (679) 3313 388, FAX (679) 3302903
EMAIL: info@nrwmacallan.com.fj

DRAIBA PRIMARY SCHOOL