

INFRASTRUCTURE ASSESSMENT AUDIT FOR SUVA – NAUSORI URBAN SCHOOLS

AOG PRIMARY (2335)

SUMMARY REPORT



TABLE OF CONTENTS

1) INSPECTION SUMMARY3

2) ASSESSMENT OF OVERCROWDING4

3) EXISTING INFRASTRUCTURE CONDITIONS5

4) WATER SANITATION HYGIENE (WASH) FACILITIES.....6

5) DISASTER RESILIENCE ASSESSMENT7

6) ACCESSIBILITY ASSESSMENT.....8



7) SUMMARY OF FINDINGS9

8) RECOMMENDATIONS.....10

9) COMPLIANCE.....10

10) APPENDIX10

1) INSPECTION SUMMARY

School Inspection Summary	
School name:	AOG PRIMARY SCHOOL
Overall condition state:	POOR
Key recommendations:	
- Overcrowding – 13 new classrooms required based on FNBC standards - Overcrowding – 5 new classrooms required based on recommended sizing (1.5m ²) - Accessibility –All buildings require accessibility ramps, accessible doorways - Disaster resilience – Windows to include cyclone shutters and roof cladding fastened with Cyclone roofing screws.	
Comments:	
Major defects were noted as follows: <ul style="list-style-type: none"> Damaged ceiling Cracks on walls Missing ramps (All buildings) Inadequate stairway width. (All buildings) Girls' toilet cubicles in poor condition. Dented and dislodged handrails. Roof cladding, gutter and roofing nails. 	
Aerial view of school	General view of school
	

School type:	Primary	✓	Secondary		Year levels	1,2,3,4,5,6,7,8
School address:	Laucala Beach state Nasinu Velau Drive Kinoya.					
School enrolment and staff figures	No. of Students (Male)	No. of Students (Female)	No. of Students with Disability	No. of Teachers (Male)	No. of Teachers (Female)	
	595	501	2	13	13	
School building arrangement	TOTAL NUMBER OF BUILDINGS: 4 B3 – 1 STOREYS / B2 – 1 STORYS / B1– SINGLE STOREYS / B4 – 2 STOREYS					
Local government area:	VELAU DRIVE KINOYA SUVA					
Date of inspection:	07 TH JUNE, 2024					
Inspection team:	ANASEINI LEDUA (AL) SHANEEL PRASAD (SP) YASH VINEET MUDALIAR (YM) DURGESH PAL (DP)					
Data collection methods	Visual inspection		✓	Onsite measurement		✓
	Interviews with school staff		✓	Drone / aerial imagery		✓
	Survey form		✓	Desktop research		✓
	Other:					
Assumptions:	NONE					
Limitations:	UNAVAILABILITY OF ALL SCHOOL DOCUMENTS SUCH AS BOUNDARY AREA.					

2) ASSESSMENT OF OVERCROWDING

An assessment for overcrowding was undertaken based on FNBC standards and 2024 enrolment data. The table below summarises the data collected through visual inspection and interrogation of enrolment data and compares this against the FNBC standard student to classroom size ratio of 2 m² per student.

Year	Stream	Number of students	Current number of classrooms	Number of extra classrooms required based on FNBC on 2024 data
1	101	40	2	1
	102	37		
2	201	37	3	1
	202	42		
	203	45		
3	301	35	3	1
	302	40		
	303	39		
4	401	41	3	1
	402	44		
	403	44		
5	501	45	3	0
	502	46		
	503	44		
6	601	50	3	1
	602	48		
	603	48		

7	701	38	4	0
	702	39		
	703	41		
	704	38		
8	801	44	4	0
	802	45		
	803	44		
	804	48		

3) EXISTING INFRASTRUCTURE CONDITIONS

Given the outlined procedure, the following observations were made:

Block Code	Length (m)	Width (m)	Height (m)	No. of Levels	Type	Room List
C	25.34	9.54	2.6	1	Timber floor joist and bearer with cladding on timber framed roof structure	- Ground Floor – 4x classrooms 1x special room and 1 x Teachers room
B	73.0	7.0	2.6	1	Concrete with cladding on timber framed roof structure	- Ground Floor – 8 x classrooms
A	65.7	7.4	2.6	1	Concrete with cladding on timber and steel framed roof structure	- Ground Floor – 7 x classrooms 1x Admin 1x canteen 1xAblution Block 1 x sick bay and 1x Library 4x Toilet Bay for boys and 7 bay for girls
D	27.9	10.5	6.8	2	Concrete with cladding on timber framed roof structure	- Ground Floor – 3x Classrooms - Top Floor – 3x Classrooms

NOTE: Toilets mentioned refers to a set of cubicles.

Summary Table for Classrooms

This table provides a quick overview of the assessment findings, helping to identify areas that need immediate attention and those that are in good condition. The following criteria was used:

- Good - No additional works / intervention required
- Fair - Remedial works required
- Poor - Demolition and replace with new

Assessment Area	Criteria	Conditions
Structural Integrity	Walls, ceiling, floor, foundation and roofs	Good
General upkeep	Exterior, interior, furniture and fixtures	Poor
Safety compliance	Fire safety, electrical safety,	Fair
Disability	Accessibility	Poor
Ventilation and lighting	Ventilations, Natural Lighting, Artificial Lighting.	Fair

Observations on Structural Elements

- **Walls and Ceiling** – There were no signs of wear and tear on walls. The walls and ceiling were well painted.
- **Floors and Foundation** – the floor and foundation for the entire school is found to be stable. There were no visible or sign of cracks or uneven surface. However, the floor is mostly covered with tiles.
- **Roofs** – the school reported that there are no leaks. It was found that roof materials are in good condition. However, some roof cladding and fastenings are partially rusted and requires upgrading works.
- **Windows** – some missing window louvre blades were recorded at various buildings
- **Cyclone** – minor roof upgrading works required to increase cyclone resilient capacity of the structures.

Existing Conditions of Building and Maintenance

- **Exterior** – the building is in fair condition as the wall, beam, column, window seal, doors, eaves, fascia boards and gutters are intact and coated with paint. The school executes periodical maintenance.
- **Interior** – the building is in fair condition as the walls, beams, columns windows, doors and ceiling are intact and coated with paint. The school executes periodical maintenance. The classrooms were found to be clean with proper waste disposal.
- **Furniture and Fixtures** – the classrooms and offices have adequate furniture and fixtures that do not impede on the function of the buildings.

Safety and compliance with standards

- **Fire Safety** – the school does not possess adequate fire safety mechanisms. Present fire Extinguishers need maintenance and commissioning. No fire hydrants and alarm systems were found. The school has Emergency exit plan and designated assembly area provisioned.
- **Electrical Safety** – The school is connected to EFL Grid. The school has surface wiring with no fault outlets. All electrical systems are measured to be safe.
- **Accessibility** – the school does not meet disability accessibility standards. The school does not have facilities such as ramps, handrails and accessible restrooms.

Lighting and Ventilation

- **Ventilation** – HVAC system (Heating, Ventilation, and Air Conditioning) is centrally located in the school, in particular, offices and Computer Labs.
- **Natural Lighting** – there are adequate number of windows installed in classrooms, that are regularly cleaned to allow natural light to enter into classrooms unobstructed.
- **Artificial Lighting** – it was found that all light fixtures are working and provides adequate illumination.

4) WATER SANITATION HYGIENE (WASH) FACILITIES

Condition of Toilets and Washrooms

The facilities have some minor defects such as:

- The cubicle doors were damaged.
- Some toilet seat pans were missing.
- Rust was found on the door hinges and steel connectors of the PVC pipe outlets in the toilet system.
- The floor and walls had damaged and missing tiles.

The WASH facilities were unclean and lacked maintenance.

TOILET CUBICLE(S)		No. of Cubicles		Toilet Ratio (1 cubicle: students)		Compliance of Student to Toilet Cubicle Ratio (FNBC).	
Building Index	Used by Years	Female	Male	Female	Male	Female Requirement (1:20) Extra Toilets?	Male Requirement (1:30) Extra Toilets?
B5	ALL year	23	22	22	28	0	0

HAND BASINS IN THE TOILET		No. of Hand Basins		Handbasin Ratio 1:		Compliance of Student to Hand Basin Ratio (FNBC).	
Building Index	Used by Years	Female	Male	Female	Male	Female Requirement (1:60) Extra Handbasins?	Male Requirement (1:60) Extra Handbasins?
B1,B2,B3, B4	All years	8	3	8	3	N/A	N/A

GENERAL OUTDOOR TAPS		No. of General Outdoor Taps	Outdoor Taps Ratio 1:	Compliance of Student to Outdoor Taps Ratio Requirement (1:60) (FNBC) Does it require additional hand basins?
Building Index	Used by Years			
B1,B2,B3,B4	All years	52	22	0

5) DISASTER RESILIENCE ASSESSMENT

This infrastructure condition assessment aims to evaluate the architectural, structural, and non-structural features of the school to ensure it is resilient to natural disasters and provides a safe learning environment for students. The assessment also identifies areas for improvement and highlights the measures already in place to enhance overall resilience. FNBC 1990 and basic loading, wind and seismic AS/NZS codes typical details were utilized during and after inspection.

Architectural

- Cyclonic Roof: The school has a cyclonic roof designed to withstand strong winds and seismic activity. However, replacement with new roof cladding and roofing screws is needed.
- Central Location: The school is centrally located, allowing easy access to main streets and relief services.

Structural

- Material Quality: The school buildings are constructed using reinforced concrete and follow acceptable engineering design principles.
- Structural Integrity: Buildings have demonstrated the capability to withstand and recover from natural disasters like earthquakes, category 3 cyclones, and floods.

Non-Structural

- Disaster Preparedness: Implementation of disaster evacuation plans, emergency exit routes, and safety protocols.
- Fire Safety: Equipped with a fire alarm system and strategically placed fire extinguishers to mitigate fire-related risks.

6) **ACCESSIBILITY ASSESSMENT**

1. **Compliance with Accessibility Standards:**

- Educational facilities did not meet accessibility standards, such as the Fiji Disable People Federation Access Audit Tool 1.0. This toolkit covers aspects like ramps, door widths, signage, and accessible routes, also the noncompliance extends beyond physical structures to digital accessibility.

2. **Facilities for Students with Disabilities:**

- Classrooms did not have adjustable seating arrangements, clear sightlines, and adequate space for mobility aids also including accessible desks and adjustable podiums.
- Laboratories are not able to accommodate students with various disabilities with the absence of adjustable lab benches, accessible sinks, and clear pathways.
- Libraries require accessible shelving, reading stations, and assistive technology (such as screen readers) to enhance library usability.
- Restrooms (WASH facilities) we're not wheelchair-accessible or have grab bars and sinks at an appropriate height.
- Common Areas: the cafeterias and outdoor spaces we're not designed inclusively. Benches, seating areas, and a few pathways are not able to accommodate everyone.

3. **Access to Classrooms, WASH Facilities, and Common Areas:**

- Classrooms do not have wide doorways and ramps to ensure access to classrooms. Additionally, acoustics are not considered for students with hearing impairments.
- WASH Facilities do not have accessible restrooms with proper signage and a clear pathway to the wash facilities.
- Common Areas like corridors, courtyards, and gathering spaces are not barrier-free and are without proper lighting and contrasting floor materials to aid navigation.

7) SUMMARY OF FINDINGS

The following summarizes the individual characteristics assessed during the Suva-Nausori school audit for AOG Primary school:

Categories of Assessment	Existing Condition / State	Required as per Standards	Gaps Observed
Existing Infrastructure Condition	<ul style="list-style-type: none"> - Structural Integrity – Columns, slabs, beams, rafters, purlins of adequate size. - General upkeep – Minor irregular maintenance. - Safety compliance- handrails where necessary. - Disability- no consideration when constructed. - Ventilation and lighting – damaged and missing lights at some sections of buildings. 	<ul style="list-style-type: none"> - Structural Integrity – Columns, slabs, beams, rafters, purlins sizes to follow FNBC 1990. - General upkeep –routine check-up as per MOE policies with major defects requiring immediate intervention. - Safety compliance- handrails, extra doors and signage where necessary. - Disability- to comply with FDPF Disability audit tool - Ventilation and lighting – adequate windows and doors required as per FNBC 1990. 	<ul style="list-style-type: none"> - Structural Integrity – Columns, slabs, beams, rafters, purlins sizes to follow FNBC 1990. - General upkeep –requires immediate intervention to major defects. - Safety compliance- safety handrails were only present in suspended floors while ground floor rails beside drain had missing rails (not fully safety compliant). FDPF requires signage which was absent from the school. - Disability- not fully compliant with FDPF Disability audit tool - Ventilation and lighting – limitations in the count of windows and lightings compared to required FNBC.
Assessment of Overcrowding	<ul style="list-style-type: none"> - The classrooms are accommodating an average of 1096/25 classrooms of 44 students. 	<ul style="list-style-type: none"> - FNBC 1990 requires classroom occupancy to have 2m² per person. Based on that, the required roll per classroom was calculated. 	<ul style="list-style-type: none"> - 15/25 classrooms were accommodating more roll than required. - Given the recommended sizing (1.5m²), about 5extra classrooms are required to address overcrowding in school.
Water Sanitation Hygiene (WASH) facilities	<p>Toilets (students: Cubicle)</p> <ul style="list-style-type: none"> - Boys – 22:1 - Girls – 23:1 <p>Taps (students: tap)</p> <ul style="list-style-type: none"> - Students – 52:22 <ul style="list-style-type: none"> - Menstrual Hygiene was present in every female washroom block 	<p>Toilets Ratio (students: Cubicle)</p> <ul style="list-style-type: none"> - Boys – 28:1 - Girls – 22:1 <p>Taps Ratio (students: tap)</p> <ul style="list-style-type: none"> - Students – 52:1 (22 taps) <p>Please note: Above number of cubicles and taps are respective of 2024 enrolment numbers. Due to variation of ratio with student population in FNBC, the initial ratio is referred ONLY for reporting.</p> <ul style="list-style-type: none"> - Menstrual Hygiene to be present in every female washroom block 	<ul style="list-style-type: none"> - Boys toilet ratio was in par with the FNBC 1990 ratio. This may hinder later on with growing population. - The girls toilet ratio exceeded the FNBC requirement indicating not enough toilet cubicles are in the school. Given the roll of girls, a total of No extra cubicles is required - The tap ratio was below the FNBC requirement indicating extra taps are in the school. - school require maintenance of rusting pipes and algae build-up in WASH facilities.
Disaster Resilience Assessment	<ul style="list-style-type: none"> - columns, beams, slabs had hairline cracks. - All roof had truss roof frames. - The windows only have burglar shutters at some sections. - Roof cladding is rusted - roofing nails show rusting. 	<p>Fiji Building Code 1990. Requirement is that roof cladding be free of rust and fastened securely with type 17 cyclonic screws with neoprene washers. Additionally, cyclone brackets to be fixed on every window frame.</p>	<ul style="list-style-type: none"> - Rusting of cladding contradicts to the cyclone certification requirement requiring replacement. - Absence of cyclone brackets are not acceptable as per the cyclone certification.
Accessibility Assessment	<ul style="list-style-type: none"> -Handrails partially damaged in corridors. - Classrooms and labs have typical door size of 0.8 – 0.9m width. - Stairway – average 0.9m width. 	<p>The following are requirements from Fiji Disabled People's Federation Access Audit Tool</p> <ul style="list-style-type: none"> - Ramps – required wherever elevation with minimum 1:8 maximum 1:20 - Walkway clearance - - Handrails to be 0.76m to 0.9m. 	<p>The following facilities are missing.</p> <ul style="list-style-type: none"> - Ramps and elevators for vertical access - Wide doorways and clear pathways - Proper signage - Wheelchair-accessible restrooms - Grab bars - Proper signage

		- Doors and Door size – minimum 0.9m. - Clearance required of 1.2m and tread width of minimum 310mm. (National Building Code Table D2.1)	- Inclusive seating areas and pathways - Proper lighting - Contrasting floor materials
--	--	---	--

8) RECOMMENDATIONS

- In order to comply with the FNBC, the school will require the following:
 - Classrooms: An additional 13 new classrooms for students in years 1-8. This expansion aims to accommodate the growing number of students and provide them with an enhanced learning environment.
- WASH Facilities: No additional cubicles for girls is required, equipped with up-to-date WASH facilities (handbasins), catering particularly to the needs of female students. These new facilities are essential to ensure hygiene and comfort. Additionally, some consideration could also be given to the boys' toilet cubicles as the ratio is in par with the FNBC ratio. The exact number could be discussed upon further analysis.

Weekly routine maintenance work and daily clean-up directive from MOE is also a critical component of the plan which includes:

- Roof repairs due to rusting of cladding, roofing nails, gutter and gutter straps.
- Plumbing fixes due to algae build up.
- New paint application on rails and walls

These maintenance activities are designed to address existing wear and tear and to ensure that the school buildings remain in good condition. It is recommended that maintenance be carried out at regular intervals, ideally every 12 months, to prevent deterioration and to maintain a safe and functional environment.

- Accessibility: Prioritize building accessibility features, such as ramps and handrails, to ensure compliance with standards. These features are vital for providing all students, including those with disabilities, with equal access to the school's facilities.

9) COMPLIANCE

Upon inspecting AOG Primary School, the following conclusions were drawn:

- **MEHA Compliance:** Compliant
- **WASH Facilities:** The school has ample taps. Additional 4 girls toilet cubicles required to comply with FNBC 1990.
- **Land Availability:** There is sufficient land for additional blocks behind AT, B2 and B3B.
- **NFA Compliance:** Compliant with NFA basic guidelines but does not have NFA certification.
- **WAF Compliance:** Adequate water supply, but no backup system for water cuts.
- **FNBC Compliance:** The school is not fully compliant with the occupancy requirements as well as the category 5 cyclone standards based on the windows and roofing requirements.
- **NDMO Compliance:** Targeting NFA and NBC compliance for safety.
- **EFL Compliance:** Assumed to be compliant with EFL standards.
- **DISABILITY Accessibility:** non-compliant

10) APPENDIX

Appendix A – AOG Primary Site Inspection Report

Appendix B – Excel Scoring Sheet

Appendix C – Land Available for Expansion

Appendix A - Site Inspection Report

INFRASTRUCTURE ASSESSMENT AUDIT FOR SUVA – NAUSORI URBAN SCHOOL

ASSEMBLIES OF GOD PRIMARY SCHOOL (REG 2335) SITE INSPECTION REPORT



Table of Contents

List of Abbreviations	3
2) SCHOOL BACKGROUND	4
3) SCHOOL SITE PLAN (DRONE IMAGERY OF SCHOOL)	7
4) VISUAL INSPECTION RESULTS	8
a) EXISTING BUILDING INFORMATION	8
b) EXISTING BUILDING INFORMATION	10
c) EXISTING BUILDING INFORMATION	12
d) EXISTING BUILDING INFORMATION	14
e) EXISTING BUILDING INFORMATION	16
5) PHOTOGRAPHIC REPORT	18

List of Abbreviations

NRWM	NRW Macallan (Fiji) Pte Ltd
MOE	Ministry of Education
TT	Tetra Tech International Development Pty Ltd
DFAT	Department of Foreign Affairs and Trade (Australia)
FEG	Free Education Grant
OHS	Occupational Health and Safety
NFA	National Fire Authority
WAF	Water Authority of Fiji
NBC	National Building Code
NDMO	National Disaster Management Office
EFL	Energy Fiji Limited

1) SCHOOL BACKGROUND

AOG School opened its doors for classes in 1962. Rev Lawrence R Larson who came to Fiji in 1960 and served as pastor of Assemblies of God was instrumental in the construction of the school. He was the first chairman of the board of Governors until Rev Ralph Elmore took over. Currently the school Education Boards which is nominated by the Assemblies of God church members both the primary school and High School.

The school Vision is to promote quality education to those nature's innovative and lifelong learners through an empowered system for a sustainable future.

The school Mission with a holistic and empowering educational system that enables all children to be independent, responsible and critical thinkers with innovative minds to society's needs and enrich the nation's future.

The school will educate the public of Assemblies of God Primary school to:

- Know God as their Creator and redeemer
- Know themselves as individuals and as socialized beings.
- Gain Knowledge and understanding in the highest order.
- Be creative and social oriented and contributor in society.

School Motto: My Utmost to his Highest.

Table 1: SCHOOL DETAILS

NAME OF SCHOOL	ASSEMBLIES OF GOD PRIMARY SCHOOL
SCHOOL REGISTRATION NUMBER	2335
SCHOOL LOCATION	LAUCALA BEACH ESTATE NASINU VELAU DRIVE KINOYA.
SCHOOL TYPE	PRIMARY SCHOOL
FEEDER SCHOOL	NO
DATE OF INSPECTION	06 TH JUNE, 2024.
MILESTONE	6/22 Schools
INSPECTED BY (TEAM 1)	ANASEINI LEDUA (AL)
	SHANEEL PRASAD (SP)
	DURGESH PAL (DP)
	YASH VINEET MUDALIAR (YM)

Table 2: SCHOOL ENROLMENT FIGURES

Year of Enrolment	Number of Students			Students with Disability	Number of Teachers		Total	Comments
	Male	Female	Total		Male	Female		
2024	595	501	1096	2	--	--	26	<ul style="list-style-type: none"> Classroom are overcrowded Student to teacher has an average ratio of 44:1 Wash Ratio 18:1
2023	563	500	1063	1	-	--	26	
2022	531	490	1021	1	-	-	26	
2021	581	350	931	N/A	-	-	26	
2020	524	480	1004	N/A	-	-	26	
2019	591	500	1091	N/A	-	-	26	

Table 3: 2024 CLASSROOM ENROLLMENT DETAILS (ONLY NOTE DOWN CLASSROOMS)

[illegible]

2) SCHOOL SITE PLAN (DRONE IMAGERY OF SCHOOL)



3) VISUAL INSPECTION RESULTS

a) EXISTING BUILDING INFORMATION

Building Index		Block C			Year built:.....Age:.....		
Type:	Single storey timber building with gable roof. Consists of: ➤ Ground Floor – 3x classrooms 1x Special Room and 1x teacher’s washroom.						No. of Levels:1
Dimensions		Length (m): 25.35		Width (m): 9.54		Height (m): 2.6m	
Existing State of Building							
REF. No.	Building Component	Good ¹	Fair ²	Poor ³	Structure Type ⁴	Comments	
1	Roof Lining			✓	Corrugated Roofing iron	Rusted at some sections.	
2	Roof Structure			✓	Timber	Structure was inaccessible due to absence of manhole	
3	Walls			✓	Timber	Partially damaged on the exterior	
4	Columns			✓	Timber	Damaged timber column	
5	Beams			✓	Timber	Column to column beam deteriorating	
6	Floor			✓	Timber	Deteriorating timber floor damaged at sections	
7	Handrails			✓	Timber	Damaged and paint peeling off have wear and tear and warps.	
8	Walkway(s)		✓		Timber	Bend when walking indicating damaged missing floor joist and bearers,	
9	Services – water supply	✓			WAF	Adequate supply with backup tank for washroom	
10	Available taps for general use	✓				# Of taps 6	Student – tap ratio = #: 1
11	Services – electricity		✓		EFL	Adequate supply/wires exposed/damaged lights	
12	Services – communication (internet)	✓				Adequate internet connections.	
13	Drainage			✓		Damaged drains/missing drains	

Comments

- **Visual defects**
- Ramp provided for disability student from year 2023/2022.
- Roof corrugated iron rust at some sections.
- Guttering missing, dented and have algae build up.
- Downpipes have algae build up with only half length in dimensions
- Timber walkway panels have wear and tear, wraps/bends when walking indicating damaged/missing floor joist and bearer.
- Electrical light, fans and power switches are missing, damaged and exposed.
- No drainage was observed. Water from guttering flowing down to earth.
- The paints on the walls were peeled off in some sections.
- Window shutters are present in almost all windows in administration section used for safety purpose only. Not compliant to cyclone certification. Some sections showed corrosion.
- Fascia board shows water damage (rotting) at some sections.

¹ Good - No additional works / intervention required

² Fair - Remedial works required – min CAT 3 standard

³ Poor - Demolition and replace with new - min CAT 4 standard

⁴ Type of structure - Timber/concrete/steel

- Walkway ceiling plyboard showed tear and water damage.
- Adequate ventilation is in all levels of the building.
- Staff Toilets are nearly maintained with adequate soap, handbasin and bins.

b) EXISTING BUILDING INFORMATION

Building Index		Block B				Year built: Age	
Type:	Single storey Gable building with gable roof. Consists of: 8x Classrooms					No. of Levels: 1	
Dimensions		Length (m): 73.0		Width (m): 7.3		Height (m): 2.6 (upto eaves)	
Existing State of Building							
REF. No.	Building Component	Good ⁵	Fair ⁶	Poor ⁷	Structure Type ⁸	Comments	
1	Roof Lining			✓	Corrugated	Rusted at some sections.	
2	Roof Structure			✓	Timber	Inadequate timber structure connection	
3	Walls		✓		Timber/ Concrete	Partially damaged on the exterior and interior	
4	Columns		✓		Steel	Damaged timber column shows deteriorating and damages.	
5	Beams		✓		Timber	Column to column beam deteriorating	
6	Floor		✓		Concrete	Concrete cracks on floor	
7	Handrails			✓	Timber	Shows signs of damaged inadequate connections	
8	Walkway(s)		✓		Concrete	Severe concrete cracks	
9	Services – water supply	✓			WAF	Adequate supply with backup tank for washroom	
10	Available taps for general use	✓				# Of taps 30	Student – tap ratio = #:
11	Services – electricity	✓				Adequate supply/wires exposed/damaged lights	
12	Services – communication (internet)	✓				Adequate internet connections.	
13	Drainage		✓			Damaged drains/missing drains	

Comments**Overcrowding****Dimensions of each classroom, labs****Visual defects**

- Fascia board damaged at sections.
- Corrugated roofing iron severely rusted at various sections.
- Valley gutters damaged and covered.
- Eave's batten was broken at some sections. Birds' nests were observed inside the eaves batten at various places.
- Classroom ceilings have holes on the plyboards.
- Internal walls had wooden partitions that displayed damages
- Roof corrugated iron rust at some sections.
- Guttering missing, dented and have algae build up.
- Downpipes have algae build up with only half length in dimensions
- Timber walkway panels have wear and tear, wraps/bends when walking indicating damaged/missing floor joist and bearer.
- Electrical light, fans and power switches are missing, damaged and exposed.

⁵ Good - No additional works / intervention required⁶ Fair - Remedial works required – min CAT 3 standard⁷ Poor - Demolition and replace with new - min CAT 4 standard⁸ Type of structure - Timber/concrete/steel

- No drainage was observed. Water from guttering flowing down to earth.
- The paints on the walls were peeled off in some sections.
- Window shutters are present in almost all windows in administration section used for safety purpose only. Not compliant to cyclone certification. Some sections showed corrosion.
- Fascia board shows water damage (rotting) at some sections.
- Absence of roof gutter.
- Electricity, internet and water is sufficient.
- 1x door entry on each side of the class
- Ramp provide to cater for disability students
- Roof cladding was a corrugated roofing iron which was newly painted and fastened at every purlin with roofing nails.
- The roof structure was a fink truss entirely made of timber (6 x 2 rafters, 3 x 2 purlins, 6 x 2 ceiling joists, 6 x 1 ridge board, 4 x 2 truss brace, 2 x 2 lateral bracing.
- Truss was connected with just nail connection without any ties or nail plates. Not fully cyclone compliance.
- 6-inch exterior concrete walls with hairline cracks on the front and side end.
- Rear wall contained visible cracks of about 600mm in length and 150mm maximum crack width on the window lintels.
- Absence of interior columns as the walls supported the weight of the building. Exterior columns on the walkways made up of 2-inch circular hollow section posts fixed to rafter and ceiling joists through anchor bolts and steel U- plates.
- Absence of ceiling joist to wall tie downs. Not cyclone compliant.
- Interior floor fully tiled with exterior walkway surface having hairline cracks at some sections. Approximately 250mm depth on top floor resting on ground.
- Window shutters are present in almost all windows in section used for safety purpose only. Not compliant to cyclone certification. Some sections showed corrosion.
- Shutters outside the classroom badly rusted and of large openings not compliant under cyclone standards.

c) EXISTING BUILDING INFORMATION

Building Index		Building A			Year built: Age:	
Type:	1x Admin 1x canteen 1x Ablution Block 1x sick bay and 1xLibrary. 7x Classrooms. 4x bay toilets boys and 7 bay toilets for girls.					No. of Levels: 1
Dimensions		Length (m): 65.7	Width (m): 7.4		Height (m): 2.6	
Existing State of Building						
REF. No.	Building Component	Good ⁹	Fair ¹⁰	Poor ¹¹	Structure Type ¹²	Comments
1	Roof Lining		✓		Corrugated	Rusted at some sections.
2	Roof Structure				Timber/steel	Inadequate timber structure connection
3	Walls		✓		Concrete	Partially damaged on the exterior and interior
4	Columns		✓		Timber/ Concrete	Partially damaged on the exterior and interior
5	Beams		✓		Timber/ Concrete	Deteriorating and algae building and physical damaged
6	Floor		✓		Concrete	Concrete cracks on floor
7	Handrails				Timber	Shows signs of damaged inadequate connections
8	Walkway(s)		✓		Concrete	Shows signs of damaged and cracks.
9	Services – water supply	✓			WAF	Adequate supply with backup tank for washroom
10	Available taps for general use	✓				# Of taps 10 Student – tap ratio = #:
11	Services – electricity	✓			EFL	Adequate supply/wires exposed/damaged lights
12	Services – communication (internet)	✓				Adequate internet connections.
13	Drainage			✓		Damaged drains/missing drains

Comments

- **Overcrowding**
- The administration block is easily accessible to guests as it is located on the right of driveway entrance to school.
- The office is clearly visible with adequate signage in the exterior and interior of the building.
- The paints on the walls were peeled off in some sections.
- There is major denting in some sections of the rear gutter.
- Excessive building material wastes around the technical department ground floor. Two-metre-wide workshop door made from recycled 2x2 timber and chain-link. High risk of safety of students.
- The water supply, electricity and internet connection are stable with sufficient lighting throughout the building.
- Insufficient lighting at the technical department section (missing tube lights)
- The toilets on the top floor neatly maintained with 1 bay each. Each toilet contains a hand basin, soap, toilet paper, tissue paper with a 600 x 800 louvre blade window for ventilation.
- Nearest boys' toilet is three blocks away from technical department classroom. Little consideration for boys' convenience.
- 1 manhole present in the admin office passage ceiling.
- Exposed v-drain with cracks on some sections of administrative block.
- Half covered exterior wall for toilets

⁹ Good - No additional works / intervention required¹⁰ Fair - Remedial works required – min CAT 3 standard¹¹ Poor - Demolition and replace with new - min CAT 4 standard¹² Type of structure - Timber/concrete/steel

- 3 bays of boy's toilets are not enough to cater for 7 Bays of classroom.
- Excessive concrete damage on the open square drain channel under the technical department section. Concrete severely chipped causing water log at various places.
- Poorly designed drainage outlet from technical department drain channel to main roadside drainage.
- Roof cladding was a corrugated roofing iron which was newly painted and fastened at every purlin with roofing nails.
- Interior floor fully tiled with exterior walkway surface having hairline cracks at some sections. Approximately 250mm depth on top floor resting on ground.
- Window shutters are present in almost all windows in administration section used for safety purpose only. Not compliant to cyclone certification. Some sections showed corrosion.
- The paint on the building is being peeled off.
- Fascia board shows water damage (rotting) at some sections.
- Absence of roof gutter.
- Kitchen is properly maintained.
- Canteen properly maintained with presence of fire extinguisher.
- Handrails have one intermediate support with no balusters indicating structure constructed to keep students off the school gardens with minimum consideration for safety.
- Fire hydrant onsite (Not working).
- Require retaining wall at rear side of the building shows signs of soil erosions.

d) EXISTING BUILDING INFORMATION

Building Index		Building D				Year built: Age:	
Type:	<ul style="list-style-type: none">• 3x Classroom for top level.• 3x Classroom Floor level.					No. of Levels: 2	
Dimensions		Length (m): 27.9		Width (m): 10.5		Height (m): 6.8 (upto eaves)	
Existing State of Building							
REF. No.	Building Component	Good ¹³	Fair ¹⁴	Poor ¹⁵	Structure Type ¹⁶	Comments	
1	Roof Lining			✓	Corrugated	Rusted at some sections.	
2	Roof Structure				Timber	Inadequate timber structure connection	
3	Walls		✓		Concrete	Partially damaged on the exterior and interior	
4	Columns		✓		Concrete	Shows signs of hairline cracks.	
5	Beams		✓		Concrete	Shows signs of hairline cracks	
6	Floor		✓		Concrete	Severe cracks and chipping around stairs.	
7	Handrails		✓		Steel	Shows signs of damaged	
8	Walkway(s)		✓		Concrete	Shows signs of damaged and cracks.	
9	Services – water supply	✓			WAF	Adequate supply with backup tank for washroom	
10	Available taps for general use	✓				# Of taps 0	Student – tap ratio = #:
11	Services – electricity		✓		EFL	Adequate supply/wires exposed/damaged lights	
12	Services – communication (internet)	✓				Adequate internet connections.	
13	Drainage			✓			

Comments

- Overcrowding
- Dimensions of each classroom, labs etc
- Visual defects
- Absence of valley gutter. Corrugation placed irregularly.
- Severe damage to eaves batten at the rear end.
- Fascia board shows algae build up.
- Holes and tear on timber walls inside classrooms.
- Rusted CHs posts at the joints
- Missing rails (especially bottom rail) at sections of railings posing safety hazard.
- Hairline cracks and chips at some sections.
- Missing lights and damaged lights and ports in some classrooms.
- The roof structure was a fink truss entirely made of timber (6 x 2 rafters, 3 x 2 purlins, 6 x 2 ceiling joists, 6 x 1 ridge board, 4 x 2 truss brace, 2 x 2 lateral bracing.
- Truss was connected with just nail connection without any ties or nail plates. Not fully cyclone compliance.

¹³ Good - No additional works / intervention required¹⁴ Fair - Remedial works required – min CAT 3 standard¹⁵ Poor - Demolition and replace with new - min CAT 4 standard¹⁶ Type of structure - Timber/concrete/steel

-Exposed starter bars at rear side of the building don't compile safety of students Handrails have one intermediate support with no balusters indicating structure constructed to keep students off the school gardens with minimum consideration for safety.

- Fire hydrant onsite (Not working).
- Require retaining wall at rear side of the building shows signs of soil erosions.

e) EXISTING BUILDING INFORMATION

Building Index		E			Year built: Age:.....		
Type:	Toilet Block					No. of Levels: 1	
Dimensions		Length (m): 28.3	Width (m): 7.5		Height (m): 2.7(upto eaves)		
Existing State of Building							
REF. No.	Building Component	Good ¹⁷	Fair ¹⁸	Poor ¹⁹	Structure Type ²⁰	Comments	
1	Roof Lining			✓	Corrugated	Rusted at some sections.	
2	Roof Structure				Timber	Structure was inaccessible due to absence of manhole	
3	Walls			✓	Concrete	Concrete walls /Minor paint peel	
4	Columns		✓		Concrete	Minor paint peel and hairline cracks	
5	Beams		✓		Concrete	Minor paint peel and hairline cracks	
6	Floor			✓	Concrete	Severe cracks and chipping	
7	Handrails			✓			
8	Walkway(s)		✓			Shows signs of damaged and cracks.	
9	Services – water supply	✓				Adequate supply with backup tank for washroom use	
10	Available taps for general use	✓				# Of taps 14	Student – tap ratio = #:
11	Services – electricity			✓		Adequate supply/wires exposed/damaged lights	
12	Services – communication (internet)	✓					
13	Drainage			✓		Damaged drains/missing drains	

Comments

- Gable roof.
- Walkways and staircases having roof to accommodate for rainy conditions.
- The paint on the building is being peeled off partially in some sections. Mainly observed in ground floor on the rear wall and front fascia boards.
- Missing gutter system on the toilet roof with partial denting in some sections.
- Interior ceiling shows damage with missing roof cover in one section of a staircase.
- One water storage tank for toilet uses behind the building.
- Building walls required re-painting works.
- Paint peel in some sections of the fascia board.
- Missing gutter system on the toilet roof with partial denting in some sections.
- Absence of window shutters throughout the building.
- Electricity and internet and water is sufficient.
- Toilets WASH easily accessible but requires some maintenance works.

¹⁷ Good - No additional works / intervention required¹⁸ Fair - Remedial works required – min CAT 3 standard¹⁹ Poor - Demolition and replace with new - min CAT 4 standard²⁰ Type of structure - Timber/concrete/steel

- Drainage adequately maintained with minor damages. Open v-drain with minor concrete damage. Missing drain cover in front facing drains.
- Adequate ventilation is in all levels of the building.
- Easily accessible to non-accessible student.
- Not accommodating to wheelchair users who require a minimum of 1m clearance.
- Absence of ramps throughout the building.
- All toilets are located at a distance away from the main walkway.
- Boys' toilet located at right end is farther away from left end classrooms. This requires boys to travel at a greater distance to reach the toilet.
- The boys and girl's toilets require cleaning.

4) PHOTOGRAPHIC REPORT

Client:	TETRA TECH INTERNATIONAL DEVELOPMENT (PTY) LTD	School Name:	ASSEMBLIES OF GOD PRIMARY
Project:	INFRASTRUCTURE PLAN FOR SUVA – NAUSORI URBAN SCHOOL.	Building Index:	C



PHOTOGRAPH No. 1: FRONT



PHOTOGRAPH No. 2: SIDE



PHOTOGRAPH No. 3: BACK



PHOTOGRAPH No. 4: SIDE



PHOTOGRAPH No. 5: INTERIOR



PHOTOGRAPH No. 6: ROOF

Client:	TETRA TECH INTERNATIONAL DEVELOPMENT (PTY) LTD	School Name:	ASSEMBLIES OF GOD PRIMARY
Project:	INFRASTRUCTURE PLAN FOR SUVA – NAUSORI URBAN SCHOOL.	Building Index:	B



PHOTOGRAPH No. 1: FRONT



PHOTOGRAPH No. 2: SIDE



PHOTOGRAPH No. 3: SIDE



PHOTOGRAPH No. 4: BACK



PHOTOGRAPH No. 5: INTERIOR



PHOTOGRAPH No. 6: ROOF SPACE

Client:	TETRA TECH INTERNATIONAL DEVELOPMENT (PTY) LTD	School Name:	ASSEMBLIES OF GOD PRIMARY
Project:	INFRASTRUCTURE PLAN FOR SUVA – NAUSORI URBAN SCHOOL.	Building Index:	A



PHOTOGRAPH No. 1: FRONT



PHOTOGRAPH No. 2: SIDE




PHOTOGRAPH No. 3: BACK



PHOTOGRAPH No. 4: SIDE



PHOTOGRAPH No. 5: INTERIOR



PHOTOGRAPH No. 6: ROOF SPACE

Client:	TETRA TECH INTERNATIONAL DEVELOPMENT (PTY) LTD	School Name:	ASSEMBLIES OF GOD PRIMARY
Project:	INFRASTRUCTURE PLAN FOR SUVA – NAUSORI URBAN SCHOOL.	Building Index:	D



PHOTOGRAPH No. 1: FRONT



PHOTOGRAPH No. 2: SIDE




PHOTOGRAPH No. 3: BACK



PHOTOGRAPH No. 4: SIDE



PHOTOGRAPH No. 5: INTERIOR



PHOTOGRAPH No. 6: ROOF SPACE

Client:	TETRA TECH INTERNATIONAL DEVELOPMENT (PTY) LTD	School Name:	ASSEMBLIES OF GOD PRIMARY
Project:	INFRASTRUCTURE PLAN FOR SUVA – NAUSORI URBAN SCHOOL.	Building Index:	Toilet Block



PHOTOGRAPH No. 1: FRONT



PHOTOGRAPH No. 2: SIDE



PHOTOGRAPH No. 3: BACK



PHOTOGRAPH No. 4: SIDE



PHOTOGRAPH No. 5: INTERIOR


DUE to roof space inaccessibility, the roof space photograph cannot be provided.

PHOTOGRAPH No. 6: ROOF SPACE

Appendix B – Excel Scoring Sheet

WEIGHTED CRITERIA		
PART A - CLASSROOM OVERCROWDING (40%)		
1	Classrooms facilitating students beyond room capacity, determined through number of students per classroom and classroom size	
	Poor - most to all classrooms are accommodating students above capacity.	32 to 40
	Criteria Item Score	40
PART B - WASH FACILITIES (20%)		
2	WASH- Student ratio based on the Fiji National Building Code (FNBC) Infrastructure Standards (10%)	
	Good - WASH-Student ratio for school toilet blocks meets or exceeds the ratio in the standard specified by FNBC.	0 to 5.9
2.1	Quality of facilities and current condition such as functionality and maintenance (10%)	
	Poor - school toilet facilities are not maintained and the physical infrastructure cause major disturbances to end users.	8 to 10
	Criteria Item Score	13.0
PART C - CONDITION OF INFRASTRUCTURE (20%)		
3	Building structure and condition of walls, floors, ceilings, overall structural integrity (10%)	
	Fair - some building structures require more intervention to improve structural integrity and condition.	6 to 7.9
3.1	Maintenance and assessment of the upkeep of facilities including painting and repairs (10%)	
	Poor - school facilities are not maintained and the physical infrastructure cause major disturbances to end users.	8 to 10
	Criteria Item Score	15.0
PART D - DISABILITY ACCESSIBILITY (10%)		
4	Accessibility features such as the presence of existing ramps, handrails, accessible toilets etc	
	Poor - School buildings and facilities do not have accessibility features.	8 to 10
	Criteria Item Score	8.0
PART E - DISASTER RESILIENCE (10%)		
5	Presence and quality of measures for disaster resilience of buildings including structural measures, cyclone shutters and fire safety systems	
	Poor - most or all school building structures are not resilient to natural disasters and do not have safety systems in place.	8 to 10
	Criteria Item Score	10.0
TOTAL CRITERIA SCORE		86.0

Appendix C – Land Available for Expansion



**NRW MACALLAN (FIJI) LTD
CONSULTING ENGINEERS**

CIVIL, STRUCTURAL, ELECTRICAL, MECHANICAL & PROJECT MANAGEMENT
79 RATU MARA ROAD, SAMABULA, SUVA
P O BOX 1208, SUVA. PHONE: (679) 3313 388, FAX (679) 3302 903
EMAIL: info@nrwmacallan.com.fj

SCHOOL NAME:

AOG PRIMARY SCHOOL